

**From:** "Gordon Webb"  
**Sent:** Tue, 9 Feb 2021 14:50:46 +1100  
**To:** "Troy Subotic" <TSubotic@wollongong.nsw.gov.au>  
**Cc:** "Peter Kellaway" <pkellaway@wollongong.nsw.gov.au>  
**Subject:** FW: Helensburgh Community Centre - floor structure replacement, subfloor drainage and subfloor ventilation improvements - UPDATE!!!  
**Attachments:** Helensburgh Community Centre (2).pdf, Australian\_Mould\_Guidelines\_2005-1.pdf, 20-12361-01-OH.pdf

Hi Troy,

To be brief we are dealing with latent conditions at HB CC.

I was not made aware of the full extent of asbestos and/or extensive mould in the sub floor area at this site, this soon became apparent on exposure of the sub floor area. Quadracon were engaged via Vendor Panel to complete this project, they requested to cut a small hatch in the floor late last year, it was immediately apparent that there was extensive mould in situ and asbestos fragments. As a matter of due diligence I had the sub floor area professionally tested which identified microbial contamination and asbestos requiring professional removal, the floor was then sealed back up again. Quadracon have been working on a safe solution as per the Clearsafes recommendations and Council direction, as such from me to Quadracon;

I appreciate your patience with this challenging project.

As you are well aware I requested a hygienist inspect the site prior to opening up the floor area, this was to investigate some potential issues. Thank you for organising a hygienist inspection and report, Council have received the Clearsafes report and I have consulted with the major stakeholders within WCC. Approximately 90% of the report mentions conditions and solutions of which Council is aware of, have considered and/or in the process of resolving, Council has confirmed a way forward for this project. To be brief, Council are committed to completing the original SOWs, the entire floor area will not be replaced within this project. Council and Quadracon need to manage this project in a step process to ensure safety and practicality for all.

- Site Access - The main hall must be isolated from the staff and public for the duration of the works – please ensure all doorways and access points are secured and NO ACCESS signage is in situ (most of this is already done).
- PPE – all personnel must use PPE as required in regard to asbestos removal, mould guidelines, confined spaces and Safework NSW.
- Confined space access – confined space Australian Standards and protocols must be adhered to as per Quadracon's confined space safety documentation.
- Asbestos removal and treatment – it looks like less than 10sq/m - asbestos removal Australian Standards and protocols must be adhered to, include continuous air monitoring, hen peck sub floor area, colour spray glue bearer/joist packers in sub floor area, asbestos disposal (receipts for Council), clearance certificate to Council.

- Flooring work “hold point” – open up floor area to allow inspection by Council to determine if a change of scope is required and also to examine other damaged areas. Inspection required by Council structural engineer, Geotech engineer and building coordinator.
- Flooring work and sub floor work – once Council approves the recommencement of work, business as usual and the works can recommence as per the SOWs (and potential change of scope).

At your earliest convenience please forward to Council any impact this may have on the program schedule.

Call me if you need further clarification.

I have a site meeting tomorrow with Quadracon, the hygienist and the demolition contractor to determine a way forward with this project, after tomorrow’s meeting Quadracon will be providing me with a variation in regards to the latent conditions and managing the site and the project safely. I have had various meetings with all the stakeholders, I have kept everyone in the loop, being my supervisor Peter Kellaway, ISP, structural engineer, Geotech engineer and Community Facilities, they are all aware of the situation and the subsequent delays.

I hope this brief helps explain the latest with this challenging project.



**Gordon Webb**  
**Coordinator Building Construction + Maintenance**  
 Post Locked Bag 8821 Wollongong DC NSW 2500  
 Phone +61242277807  
 Email [gwebb@wollongong.nsw.gov.au](mailto:gwebb@wollongong.nsw.gov.au) • [www.wollongong.nsw.gov.au](http://www.wollongong.nsw.gov.au)  
Our Values  SUSTAINABLE  COURAGE  RESPECT  INTEGRITY  ONE TEAM





---

**From:** Gordon Webb

**Sent:** Wednesday, 23 December 2020 12:56 PM

**To:** Jeff Hunt <[jeff.hunt@quadracon.com.au](mailto:jeff.hunt@quadracon.com.au)>

**Cc:** Andrew McKenzie <[andrew.mckenzie@quadracon.com.au](mailto:andrew.mckenzie@quadracon.com.au)>; Leeca Horsman <[LHorsman@wollongong.nsw.gov.au](mailto:LHorsman@wollongong.nsw.gov.au)>; Jan Noble <[JNoble@wollongong.nsw.gov.au](mailto:JNoble@wollongong.nsw.gov.au)>; Peter Kellaway <[pkellaway@wollongong.nsw.gov.au](mailto:pkellaway@wollongong.nsw.gov.au)>

**Subject:** FW: Helensburgh Community Centre - floor structure replacement, subfloor drainage and subfloor ventilation improvements - UPDATE!!!

Hi Jeff,

Thanking you, it is looking like we should block out the user groups until April 2021 atm. Once you have compiled the costing submission please forward that through to me asap.

Just to let you know that I will be on leave from 26/12 to 4/1 during the Council Xmas shut down period. During this time if you need any assistance please contact either Trent Doering on 0401743698 or Daniel Cappetta on 0447003465. Irrelevant really but just in case....

Have a good Xmas to all at Quadracon!!!!

regards



**Gordon Webb**

**Coordinator Building Construction + Maintenance**

**Post Locked Bag 8821 Wollongong DC NSW 2500**

**Phone +61242277807**

**Email [gwebb@wollongong.nsw.gov.au](mailto:gwebb@wollongong.nsw.gov.au) • [www.wollongong.nsw.gov.au](http://www.wollongong.nsw.gov.au)**

**Our Values**  SUSTAINABLE  COURAGE  RESPECT  INTEGRITY  ONE TEAM



---

**From:** Jeff Hunt <[jeff.hunt@quadracon.com.au](mailto:jeff.hunt@quadracon.com.au)>

**Sent:** Wednesday, 23 December 2020 12:13 PM

**To:** Gordon Webb <[GWebb@wollongong.nsw.gov.au](mailto:GWebb@wollongong.nsw.gov.au)>

**Cc:** Andrew McKenzie <[andrew.mckenzie@quadracon.com.au](mailto:andrew.mckenzie@quadracon.com.au)>; Murray Finch <[murray.finch@quadracon.com.au](mailto:murray.finch@quadracon.com.au)>; Leeca Horsman <[LHorsman@wollongong.nsw.gov.au](mailto:LHorsman@wollongong.nsw.gov.au)>

**Subject:** RE: Helensburgh Community Centre - floor structure replacement, subfloor drainage and subfloor ventilation improvements - UPDATE!!!

**[EXTERNAL EMAIL]** This email was sent from outside of Wollongong City Council – be cautious, particularly with links and attachments.

Hi Gordon

Please see our attached updated Program, to include the latest additional steps required for the mould/asbestos removal, hold points, Council Engineer inspections date. We have allowed an estimated timeframe of 1 x week for any additional works which may eventuate from the Engineers inspection. The Engineer inspection date is noted at Monday February the 7<sup>th</sup>.

We are also putting together a costing submission that will occur due to the need to comply with:

- Recommendations set out in Item 9/ page 16 of Clearsafes report (attached)
- Australian Mould guide lines (attached)

Happy to discuss further, and please advise of contact details for your colleague who will be covering you over the break.

Kind Regards



Jeff Hunt, Operations Manager NSW  
**Quadracon Building** M: 0421 055 224  
 W: [www.quadracon.com.au](http://www.quadracon.com.au) T: 1800 845 101  
 NSW Office: 18/17 Cemetery Rd, Helensburgh NSW 2508

Clicking "print" = 1 second. Growing a tree = 40 years! Think green and read from the screen!



PRIVATE AND CONFIDENTIAL If you have received this email in error, please notify us immediately by telephone or email and delete it.

---

**From:** Gordon Webb <[GWebb@wollongong.nsw.gov.au](mailto:GWebb@wollongong.nsw.gov.au)>  
**Sent:** Tuesday, 22 December 2020 7:27 AM  
**To:** Andrew McKenzie <[andrew.mckenzie@quadracon.com.au](mailto:andrew.mckenzie@quadracon.com.au)>  
**Cc:** Jeff Hunt <[jeff.hunt@quadracon.com.au](mailto:jeff.hunt@quadracon.com.au)>; Leeca Horsman <[LHorsman@wollongong.nsw.gov.au](mailto:LHorsman@wollongong.nsw.gov.au)>  
**Subject:** RE: Helensburgh Community Centre - floor structure replacement, subfloor drainage and subfloor ventilation improvements - UPDATE!!!

Hi Andrew,

I am fielding a few questions in regard to this project and Council require some feedback so Council can shuffle about the user groups if needed.

At your earliest convenience please forward to Council any impact this (below email details) may have on the program schedule, an answer by COB Wednesday would be much appreciated.

P.S. I will be on leave 11/1 to 22/1 and need to brief another coordinator asap.

regards



**Gordon Webb**  
**Coordinator Building Construction + Maintenance**  
 Post Locked Bag 8821 Wollongong DC NSW 2500  
 Phone +61242277807  
 Email [gwebb@wollongong.nsw.gov.au](mailto:gwebb@wollongong.nsw.gov.au) • [www.wollongong.nsw.gov.au](http://www.wollongong.nsw.gov.au)  
**Our Values** SUSTAINABLE COURAGE RESPECT INTEGRITY ONE TEAM




---

**From:** Gordon Webb  
**Sent:** Wednesday, 16 December 2020 10:58 AM  
**To:** Andrew McKenzie <[andrew.mckenzie@quadracon.com.au](mailto:andrew.mckenzie@quadracon.com.au)>  
**Cc:** Jeff Hunt <[jeff.hunt@quadracon.com.au](mailto:jeff.hunt@quadracon.com.au)>  
**Subject:** Helensburgh Community Centre - floor structure replacement, subfloor drainage and subfloor ventilation improvements - UPDATE!!!

Hi Andrew (Quadracon),

I appreciate your patience with this challenging project.

As you are well aware I requested a hygienist inspect the site prior to opening up the floor area, this was to investigate some potential issues. Thank you for organising a hygienist inspection and report, Council have received the Clearsafe report and I have consulted with the major stakeholders within WCC. Approximately 90% of the report mentions conditions and solutions of which Council is aware of, have considered and/or in the process of resolving, Council has confirmed a way forward for this project. To be brief, Council are committed to completing the original SOWs, the entire floor area will not be replaced within this project. Council and Quadracon need to manage this project in a step process to ensure safety and practicality for all.

- Site Access - The main hall must be isolated from the staff and public for the duration of the works – please ensure all doorways and access points are secured and NO ACCESS signage is in situ (most of this is already done).
- PPE – all personnel must use PPE as required in regard to asbestos removal, mould guidelines, confined spaces and Safework NSW.
- Confined space access – confined space Australian Standards and protocols must be adhered to as per Quadracon’s confined space safety documentation.
- Asbestos removal and treatment – it looks like less than 10sq/m - asbestos removal Australian Standards and protocols must be adhered to, include continuous air monitoring, hen peck sub floor area, colour spray glue bearer/joist packers in sub floor area, asbestos disposal (receipts for Council), clearance certificate to Council.
- Flooring work “hold point” – open up floor area to allow inspection by Council to determine if a change of scope is required and also to examine other damaged areas. Inspection required by Council structural engineer, Geotech engineer and building coordinator.
- Flooring work and sub floor work – once Council approves the recommencement of work, business as usual and the works can recommence as per the SOWs (and potential change of scope).

At your earliest convenience please forward to Council any impact this may have on the program schedule.

Call me if you need further clarification.

regards



**Gordon Webb**

**Coordinator Building Construction + Maintenance**

**Post Locked Bag 8821 Wollongong DC NSW 2500**

**Phone +61242277807**

**Email [gwebb@wollongong.nsw.gov.au](mailto:gwebb@wollongong.nsw.gov.au) • [www.wollongong.nsw.gov.au](http://www.wollongong.nsw.gov.au)**

**Our Values** SUSTAINABLE COURAGE RESPECT INTEGRITY ONE TEAM





# Helensburgh Community Centre

[illegible]

# **AUSTRALIAN MOULD GUIDELINE**

## **AMG-2005-1**

Editors  
**Dr Peter Kemp &  
Dr Heike Neumeister-Kemp**

First Edition March 2005

Those working in the Mould Industry should read this document in conjunction with the ACMR / ACMI Reference Manual for Australian Certified Mould Remediators and Investigators.

**Please note that this is not an Australian Standard as published by Standards Australia. This document is currently a guideline and is intended to become an industry based standard.**

**This document is in review and its contents will be subject to change.**

**Positions on the review panel are open for application. Please contact the editors if you feel you can participate by either revising or by contributing further material to this document.**

#### **First Edition**

Published March 2005

**Editors: Dr Peter Kemp and Dr Heike Neumeister-Kemp**

*Copyright © 2005 by Mycologia Australia Pty Ltd. All rights reserved. No part of this publication may be used or reproduced in any manner whatsoever without the explicit written permission from Mycologia Australia Pty Ltd. Exceptions to the copyright are small sections reproduced in reports or articles that are quoted from or referenced to this original source.*

#### **Mycologia Australia Pty Ltd**

1/454 Scarborough Rd., Osborne Park, WA 6017, Australia

Phone: +61 (0)428 43 8501  
Email: [mycologia@mould.com.au](mailto:mycologia@mould.com.au)  
Web: [www.mould.com.au](http://www.mould.com.au)

Printed in Australia

## DISCLAIMER

All mould workers who are using this document must keep in mind that developments in the mould industry are advancing rapidly. It is critical to keep ahead of these developments and modify your practices accordingly. Commonsense, experience and professional judgment should be used at all times to determine that correct levels of PPE, containment and hazard communication are used.

The authors have not personally independently tested and verified all the suggested practices and assessment or judgment strategies described in this document.

This document includes the experience and knowledge of local mould professionals and material and information from a review of current international guidelines and standards on dealing with mould contamination. The reference documents used in the writing of this standard are listed in the bibliography. In cases where information may appear to be similar to that found in other documents, it should be kept in mind that the Authors of this document have participated in the writing of many of these documents. There are basic hazard requirements when dealing with mould that are universal.

While other international standards and guidelines are referred to in this document, this document can be used as a guide that has been tailored to Australian conditions by Australian Professionals and Academics.

## Limitations

The authors expressly disclaim, and shall not be liable for, any and all damages of any nature whatsoever, whether direct or indirect, arising from or relating to the publication, use of or reliance on the information contained in this Guideline and Reference Manual, including without limitation any and all special, indirect, incidental, compensatory, consequential, punitive or other damages (including injury, damages for personal and/or

bodily injury, property damage, loss of business, loss of profits, litigation or the like), whether based upon breach of contract, breach of warranty, tort (including negligence and gross negligence), product liability or otherwise, even if advised of the possibility of such damages. The forgoing of negation of damages is a fundamental element of the use of the information contained in this Guideline and Reference Manual and this document would not be published without such limitations.

The authors make no representations, warranties or guarantees as to the accuracy or completeness of any information contained in this Guideline and Reference Manual or the compliance with any applicable statutes, laws, rules or regulations. All warranties, express or implied, are disclaimed, including without limitation, any and all warranties concerning the accuracy or completeness of the information, its fitness or appropriateness for a particular purpose or use, its merchantability and its non-infringement of any intellectual property rights.

In publishing this document, the authors are not undertaking to render scientific, professional, medical, legal or other advice or services for or on behalf of any person or entity or to perform any duty owed by any person or entity to someone else. Any and all use of or reliance upon this Guideline and Reference Manual is at the user's own discretion and risk. Anyone using this document should rely on his or her own independent judgment or, as appropriate, seek the advice of a competent professional in determining the exercise of reasonable care in any given situation.

The authors have no power, nor do they undertake, to police or enforce compliance with the contents of this document. The authors do not list, certify, test, inspect or verify service or product compliance with this document. Any certification or other statement of compliance with the requirements of this document shall not be attributable to the authors and is solely the responsibility of the certifier or maker of the statement.

# TABLE OF CONTENTS

|           |                                                                                                  |           |
|-----------|--------------------------------------------------------------------------------------------------|-----------|
| <b>1</b>  | <b>PREScribed ILLNESSES &amp; DUTY OF CARE .....</b>                                             | <b>6</b>  |
| 1.1       | BIOHAZARD COMMUNICATION STRATEGY .....                                                           | 6         |
| 1.2       | HEALTH SYMPTOMS AND COMPLAINTS RELATED TO MOULD DAMAGE.....                                      | 6         |
| <b>2</b>  | <b>MOULD AND INDOOR AIR QUALITY .....</b>                                                        | <b>7</b>  |
| <b>3</b>  | <b>IDENTIFYING MOULD GROWTH INDOORS .....</b>                                                    | <b>7</b>  |
| 3.1       | GATHERING INFORMATION.....                                                                       | 7         |
| 3.1.1     | Health Complaints.....                                                                           | 7         |
| 3.2       | ASSESSING MOULD DAMAGE.....                                                                      | 7         |
| 3.2.1     | Information Gathering Questionnaire Checklists.....                                              | 7         |
| 3.2.2     | Initial Risk Assessment.....                                                                     | 8         |
| 3.2.3     | PPE for Initial Inspection.....                                                                  | 8         |
| 3.2.4     | Visual Inspection.....                                                                           | 8         |
| 3.2.5     | Mould Sampling as Part of an Assessment.....                                                     | 8         |
| 3.2.6     | Basic Sampling Techniques and Principles.....                                                    | 8         |
| 3.2.7     | Taking Moisture Readings.....                                                                    | 8         |
| 3.2.8     | Surface Sampling.....                                                                            | 8         |
| 3.2.9     | Bulk Dust and Material Sampling.....                                                             | 8         |
| 3.2.10    | Airborne Sampling.....                                                                           | 9         |
| 3.2.11    | The Importance of Species Identification.....                                                    | 9         |
| 3.2.12    | Analysis of Mould Samples.....                                                                   | 9         |
| <b>4</b>  | <b>THE FUNDAMENTALS OF MOULD REMEDIATION.....</b>                                                | <b>9</b>  |
| <b>5</b>  | <b>CONTAINMENT PROCEDURES TO PREVENT CROSS CONTAMINATION.....</b>                                | <b>9</b>  |
| 5.1       | REMOVAL OF CONTAMINATED MATERIALS .....                                                          | 9         |
| 5.2       | REMOVAL OF BUILDING CONTENTS.....                                                                | 10        |
| 5.2.1     | Assessment.....                                                                                  | 10        |
| 5.2.2     | Removal of Contents from Affected Areas.....                                                     | 10        |
| 5.2.3     | Inventory, Packing, Transport and Storage.....                                                   | 10        |
| <b>6</b>  | <b>MOULD CLEANING PROCEDURES.....</b>                                                            | <b>10</b> |
| 6.1       | CLEANING LOCATION .....                                                                          | 10        |
| 6.2       | OUTDOORS VERSUS MULTI-CHAMBER CLEANING.....                                                      | 10        |
| 6.3       | MOULD CLEANING & REMOVAL STRATEGIES.....                                                         | 10        |
| 6.3.1     | Air-Based Methods (recommended).....                                                             | 10        |
| 6.3.2     | Liquid-Based Methods (recommended).....                                                          | 10        |
| 6.3.3     | Chemical Based Methods (not recommended).....                                                    | 10        |
| 6.3.4     | Abrasive Methods (not recommended).....                                                          | 11        |
| 6.3.5     | Appearance Enhancement (not recommended).....                                                    | 11        |
| 6.3.6     | Encapsulation (not recommended).....                                                             | 11        |
| 6.4       | REMIEDIATING MATERIALS .....                                                                     | 11        |
| 6.4.1     | Non Porous and Semi-Porous Materials.....                                                        | 11        |
| 6.4.2     | Porous Materials.....                                                                            | 11        |
| 6.4.3     | Odour Control.....                                                                               | 11        |
| 6.5       | VERIFICATION OF REMEDIATION EFFECTIVENESS .....                                                  | 11        |
| <b>7</b>  | <b>MOULD DAMAGE CLASSIFICATION SYSTEM.....</b>                                                   | <b>11</b> |
| 7.1       | BUILDING CLASS 1 - NORMAL.....                                                                   | 11        |
| 7.2       | BUILDING CLASS 2 - LOCAL AREA LESS THAN 1 m <sup>2</sup> (CLEANING TO REMOVE MOULD).....         | 12        |
| 7.3       | BUILDING CLASS 3 - LIMITED VISIBLE MOULD GROWTH TO LESS THAN 10 m <sup>2</sup> (SMALL JOBS)..... | 12        |
| 7.4       | BUILDING CLASS 4 - EXTENSIVE VISIBLE GROWTH GREATER THAN 10m <sup>2</sup> (LARGE JOBS).....      | 12        |
| 7.5       | BUILDING CLASS 5 - STRONG INDICATION OF MOULD BUT NO VISIBLE EVIDENCE .....                      | 13        |
| 7.6       | BUILDING CLASS 6 - CROSS CONTAMINATION .....                                                     | 13        |
| 7.7       | BUILDING CLASS 7 HVAC SYSTEMS.....                                                               | 14        |
| 7.8       | BUILDING CLASS 7 - CLEAN ROOM.....                                                               | 14        |
| <b>8</b>  | <b>PPE CLASSIFICATION SYSTEM.....</b>                                                            | <b>14</b> |
| 8.1       | PPE LEVEL 1 .....                                                                                | 14        |
| 8.2       | PPE LEVEL 2 .....                                                                                | 14        |
| 8.3       | PPE LEVEL 3 .....                                                                                | 14        |
| 8.4       | PPE LEVEL 4 .....                                                                                | 15        |
| <b>9</b>  | <b>GLOSSARY .....</b>                                                                            | <b>16</b> |
| <b>10</b> | <b>BIBLIOGRAPHY AND REFERENCE DOCUMENTS.....</b>                                                 | <b>18</b> |

## 1 PRESCRIBED ILLNESSES & DUTY OF CARE

It is recommended that any area undergoing mould remediation be unoccupied during cleaning or remediation works.

In most cases it should not be necessary to evacuate people from adjacent areas as long as correct containment procedures are adhered to.

However, it is highly recommended that the people with the following health categories should be advised that temporary relocation would be in their best interests:

1. Infants less than 12 months old, and children less than 2 years old
2. People with compromised immune systems
3. People with chronic inflammatory lung disease such as:
  - a. Asthma
  - b. Hypersensitivity pneumonitis, and
  - c. Severe allergies
4. People recovery from recent surgery

Failure to inform or evacuate people in these conditions may lead to a serious breach of your duty of care. The immune system of children less than 2 years old may not be fully developed and there is evidence that Kawasaki syndrome is related to wet cleaning methods on carpets.

### 1.1 BIOHAZARD COMMUNICATION STRATEGY

When the remediation work involves a Grade 4 Building, then the building's owner, manager or the employer should notify occupants in the affected areas that mould growth requiring remediation has been detected. This should include a description of the basic results from testing and analysis, the type of remedial works that will be performed, and a schedule for completion.

It may be useful to conduct group meetings to communicate these matters and to allow open discussion with the affected occupants.

Individuals that may have health problems associated with exposure to mould should be advised to seek medical advice from qualified practitioners in occupational or environmental medicine or related disciplines that are knowledgeable about mould health hazards. Any individual that requires medical assessment should be provided with a copy of all inspection and sampling results and interpretations to take with them to their medical practitioners.

### 1.2 HEALTH SYMPTOMS AND COMPLAINTS RELATED TO MOULD DAMAGE

This section has been provided as a guide to understanding when complaints of odours or health symptoms reported by either occupants or mould remediation workers that may be due to the presence of mould growth. This is particularly useful for Grade 5 Buildings where there is little obvious evidence of mould damage. If any of the following symptoms appear to be related to time spent in the building then they should be duly noted and recorded.

1. Discomfort
2. Eye irritation
3. Runny nose
4. Sneezing
5. Coughing
6. Nausea / Diarrhoea
7. Headaches
8. Fatigue
9. Inability to concentrate
10. Constriction of air passages
11. Skin irritations
12. Congestion
13. Shortness of breath
14. Wheezing
15. Aggravation of asthma

## 2 MOULD AND INDOOR AIR QUALITY

Normally, our everyday exposure to airborne fungi in the outdoor air presents little or no risk to our health. However, the airborne fungi in the artificial environments of our buildings and dwellings have an altered composition, which can create an environment with the potential to greatly affect human health. This has led to the understanding that fungi can be a major cause of both illness and the severity of general symptoms, such as sick building syndrome (SBS), which are related to the amount of time spent indoors.

All fungi are initially microscopic in size with most spores ranging in size from 2 to 20 µm (microns). There are an enormous number of fungi with over 6000 genera and only 69,000 species have been described out of an estimated total of around 1.5 million species.

Many of the visible manifestations of fungi are commonly known and include yeasts, mould growth, mildew, large mushrooms, puffballs and bracket fungi. These are all the result of the convergence of millions of individual fungal units coming together to create larger structures.

The terms mould and fungi are used interchangeably. However that is more to do with their common usage. Normally moulds only refer to those fungi with a mycelial (filamentous) type of growth.

Fungi are eukaryotic organisms and share many basic characteristics of genetic makeup with humans. This is why chemical treatment to control fungal contamination should be very carefully considered before their widespread application is considered.

The study of fungi is called Mycology. A mycologist is one who can identify fungal species and has an understanding of fungal ecology. The two main branches of mycology are Medical mycology and Environmental Mycology. Only an Environmental Mycologist should be consulted for identifying indoor and outdoor fungal species and for understanding the ecology of mould contamination in buildings.

## 3 IDENTIFYING MOULD GROWTH INDOORS

A methodical approach should be taken towards mould work for reasons include ensuring personal safety, duty of care, and legal requirements. The first step is to gather information from the client and background information on the situation being investigated. Second step will be a site visit and inspection. The third step is to establish what procedures will be required to successfully deal with any moisture or mould damage problems identified.

### 3.1 GATHERING INFORMATION

The nature of the initial contact will determine the type of the job at hand and will depend on your abilities, experience and your ethics. The profession that was called first will greatly affect the direction and outcomes of the project. It is important to establish at the outset who is legally responsible for the situation at hand.

#### 3.1.1 Health Complaints

In situations where there is a Building of Grade 3, 4 or 5 and the client or occupants complain of health symptoms, a medical assessment or contract the services of an Indoor Air Quality Professional for an indoor environmental assessment (IEA).

### 3.2 ASSESSING MOULD DAMAGE

The initial inspection will include gathering information, making a visual inspection, and taking moisture readings. From this you will then need to determine which Building Grade of Mould damage is present.

#### 3.2.1 Information Gathering Questionnaire Checklists

To help gather appropriate information and thereby judge the level of a mould situation, it can be useful to use a questionnaire checklist. The essential elements of the questionnaire include property details; use of other professions or services; background information; mouldy odours or visible mould growth; complaints or health symptoms; and major illnesses of occupants. See the reference guideline for a detailed list of information.

### 3.2.2 Initial Risk Assessment

Anyone dealing with mould on a daily basis needs to tackle each job in a manner. Failure to use a professional and methodical approach to mould work can result in injury to workers, inspectors and occupant from exposure to mould allergens or toxins. The initial contact with any job is critical in ensuring a safe work environment.

The information you gather from the questionnaire checklist will determine the Building Grade, sampling strategy and OHS issues (PPE and containment). In situations of Building Grade 4 or 5, or where there are severe health symptoms or people at risk, then all work should be directed by an experienced mould inspector or IAQ assessor. Individuals with mould related illnesses may be directed to be evacuated from the building.

### 3.2.3 PPE for Initial Inspection

An appropriate level of PPE should always be worn by those undertaking inspections or remediation work. This includes guests invited to inspect the damage or remediation works such as building owners or managers etc.

### 3.2.4 Visual Inspection

An on-site visual inspection is the most important step to identify mould problems and for determining a remediation strategy. Important surfaces to inspect include porous materials. It is important to inspect for hidden growth behind furnishings or in building cavities. Any mechanical ventilation system should be inspected for moisture or mould damage.

Evidence of damage that should be recognisable during a visual inspection should include visible mould growth; surface condensation; flooding events & accidental spills; and High humidity. In situations where it is not possible to perform extensive inspection there may be "discovery" of hidden mould damage. All parties with vested interests should be made aware that additional inspection may be required. Discovery of hidden damage should be documented.

### 3.2.5 Mould Sampling as Part of an Assessment

There are a number of situations where it would be normal to consider taking mould samples as part of the initial assessment. These include wide spread mould growth; mould odours; wet or damp materials that were not dried within 48 hours; health or symptoms or complaints; for quality control; for health risk assessment; and for species identification.

### 3.2.6 Basic Sampling Techniques and Principles

Sampling is not always required. Where a situation is driven by medical or legal reasons then mould sampling can be used to establish either exposure or baseline contamination.

Moisture measurements should be the first type of measurements taken. Mould sampling should begin with relatively simple surface samples and can include bulk samples and air samples on larger jobs. All sampling should be done in conjunction with a mycological laboratory as they will have specific handling and shipping requirements.

### 3.2.7 Taking Moisture Readings

Only a person trained in moisture measuring techniques should determine the moisture content or moisture profile of a situation. The aim of taking moisture measurement is to establish the extent of moisture damage; to provide an indicator of hidden mould damage; and for quality control.

### 3.2.8 Surface Sampling

Only a person trained in mycological sampling techniques should perform surface sampling. Surface samples are the next level of testing after moisture readings. They can aid in identifying fungal species especially in cases where spores might be surface bound (not detected by air samples). The basic types of surface samples include Surface Swab samples; RODAC Plate samples; and Tape Lift-off Samples.

Other surface sampling methods may be available through a mycological laboratory. A mycological laboratory should be consulted for specific sampling and delivery instructions.

### 3.2.9 Bulk Dust and Material Sampling

Only a person trained in mycological sampling techniques should perform bulk sampling. Bulk sampling can be useful in detecting a wide range of fungal species. This method is typically performed either using a vacuum cleaner on carpets and textile surfaces, or to simply scrape off surface material. Small pieces of material can also be removed for analysis. However, local area containment procedures should be followed when removing material from known or suspected mouldy surfaces.

Other bulk sampling methods may be available through your mycological laboratory. They should also be consulted for specific sampling and delivery instructions.

### 3.2.10 Airborne Sampling

Only a person properly trained in advanced mycological sampling techniques should perform airborne mould sampling. Airborne sampling for mould is not part of a routine assessment. A qualified Mould Inspector or IAQ Assessor should be consulted in situations where health symptoms are related to mould or to time spent in a building.

The reasons for conducting airborne sampling include when the health symptoms are related to either mould exposure or to time spent in a building; as part of a detailed risk assessment; where mouldy odours are present but no apparent visible growth; as a part of clearance testing after remediation works.

Indoor air samples for mould should be conducted together with an outdoor air sample as a reference location. The comparison of species between the indoors and the outdoors is used to determine the source of fungal contamination. The type of fungal contamination whether hydrophilic or xerophilic can also be determined. Other air sampling methods may be available through your mycological laboratory. They should also be consulted for specific sampling and delivery or shipping instructions.

### 3.2.11 The Importance of Species Identification

The identification of mould species is critical as different species impact on both human health and building infrastructure in different ways and to different degrees. In general, the species in the indoor air should be similar to that in the outdoor air. When the indoors presents a mixture of fungal species that is fundamentally different from the outdoor air, then this represents an altered exposure to fungi and the presence of an interior source of fungi.

### 3.2.12 Analysis of Mould Samples

Mould samples should only be analyzed for fungal species by an experienced mycologist or microbiologist with training in environmental mycology. A laboratory should have a person that is qualified to analyse fungi; should have quality control data on hand and a written quality assurance plan; and should provide a thorough explanation of the analytical interpretation and results.

## 4 THE FUNDAMENTALS OF MOULD REMEDIATION

In all situations concerning mould growth indoors that requires remediation, the underlying cause of moisture that is supporting the growth must be repaired or fungal growth will re-occur. There should be an emphasis in the remediation works for the cause of moisture damage to be permanently repaired so that water damage does not re-occur.

It should be kept in mind that the goal of mould remediation is not to sterilise surfaces, but to return surfaces to their normal state before contamination. It should be kept in mind that the containment, PPE, hazard communication, and cleaning guidelines in this document are not definitive. Each remediation job needs to be assessed on its own merits and the persons performing the remediation works should ensure that adequate protection measures are taken.

## 5 CONTAINMENT PROCEDURES TO PREVENT CROSS CONTAMINATION

The remediation area should not be occupied. Except for large jobs (building Grade 4/5) it should not be necessary to evacuate people from adjacent areas if containment procedures are correctly applied. However it is recommended that persons with Prescribed Illnesses listed on page 6 should be informed or removed from adjacent areas.

### 5.1 REMOVAL OF CONTAMINATED MATERIALS

Caution to prevent cross contamination is required when handling contaminated materials that are being removed for disposal or for decontamination off-site. Materials should be wrapped in plastic and seal with tape.

Materials and items that are to be retained but require remediation should be transported to an off-site facility wrapped in plastic. The items or materials should then be immediately removed from the plastic wrapping and the plastic discarded in normal waste disposal. Remediation should begin immediately according to the material type being remediated.

Materials and items that are to be disposed should be placed gently in a covered disposal unit / bin. Contaminated materials should never be thrown from a distance into a disposal unit.

Disposal units and bins should not be located close to openings such as windows or doors including those of neighbouring properties. There are no requirements for specialised type of disposal unit for mouldy materials.

## **5.2 REMOVAL OF BUILDING CONTENTS**

### **5.2.1 Assessment**

Whether contaminated contents can be restored depends on their condition; material type; the cost of remediation; financial value or cost of replacement; and other types of value such as sentimental, legal, cultural, artistic, or historical etc.

Restore items that can be cleaned and returned to the client. Dispose items that will not be cleaned. Preserve with risk Assignment items that are irreplaceable but cannot be remediate completely.

All those with vested interests should be involved in the decision as to whether contents should be restore or disposed of.

### **5.2.2 Removal of Contents from Affected Areas**

Avoid cross contamination when moving contents. Contaminated contents must be decontaminated or appropriately packaged when moved in or through uncontaminated areas. Contents should never be stored in plastic or sealed containers.

### **5.2.3 Inventory, Packing, Transport and Storage**

A detailed inventory should be made of the contents before removal. Storage conditions should be dry and otherwise minimize conditions favourable to mould growth. Remediation should proceed as soon as practical to avoid further damage and mould growth. The clean contents should not be returned to a contaminated area.

## **6 MOULD CLEANING PROCEDURES**

The goal of mould cleaning is to bring items and materials back to normal (before contamination) conditions. The purpose is not to sterilize an item or necessarily improve its appearance.

### **6.1 Cleaning Location**

On-site cleaning eliminates the cost of packing, transport and storage but may extend the remediation period and has an increased risk of cross-contamination. In-plant cleaning minimizes the time before structural drying work can start, which can drastically reduce the time required to reinstate the property back to conditions prior to the mould contamination.

### **6.2 Outdoors versus Multi-chamber Cleaning**

When cleaning contents outdoors without containment enough distance must be provided to any adjacent buildings, air intakes or unprotected people. Remediation workers must wear appropriate PPE.

### **6.3 Mould Cleaning & Removal Strategies**

A cleaning method should be chosen with the aim of producing the least amount of dust possible to limit workers exposure. More than one method may be necessary. Old buildings potential contain lead based paints and only should be properly assessed and remediate by specially trained personnel in hazardous material handling.

#### **6.3.1 Air-Based Methods (recommended)**

Air based methods physically remove contamination by vacuuming off or blasting off with air to dislodge contaminants and include HEPA filter vacuum cleaning; air washing; laminar-flow; and down draft cleaning tables.

#### **6.3.2 Liquid-Based Methods (recommended)**

Liquid-Based Methods use water combined with the mechanical action of cleaning and include damp-wiping with a detergent, vinegar solution or 70% alcohol solution; ultrasonic cleaning; steam cleaning; low pressure flushing, and high-pressure washing.

#### **6.3.3 Chemical Based Methods (not recommended)**

The use of surface chemical treatments is not recommended as they appear to have limited effect and introduce further chemical pollution into the indoor environment. Chemical Based Methods rely on toxic substances to kill the fungal growth and do not by themselves remove the contamination. These include: anti fungal / microbial agents; gaseous, vapour phase or aerosolized biocides; Ozone, Bleach, Alcohol (100%), quaternary ammonia, formaldehyde etc; and pH changing acidic or alkaloid treatments.

The use of gaseous, vapour phase or aerosolised biocides is not recommended. Using chemicals in this manner can cause adverse health effects in individuals returning to a site and occupants in adjacent areas. The benefits of this treatment are unproven.

#### **6.3.4 Abrasive Methods (not recommended)**

These rely on the use of a medium to physically dislodge contaminants. These methods are not recommended in general due to the potential for damaging surface structure, which can aid in degrading the material and thereby aid future fungal attack. Old buildings potential contain lead based paints and only should be remediated by specially trained personnel in hazardous material handling.

#### **6.3.5 Appearance Enhancement (not recommended)**

These are not cleaning methods and are not recommended and include polishing, waxing and buffing.

#### **6.3.6 Encapsulation (not recommended)**

These are not cleaning methods and are not recommended and include application of coating over porous or semi-porous material; and lamination of irreplaceable documents or photos.

### **6.4 Remediating Materials**

#### **6.4.1 Non Porous and Semi-Porous Materials**

Non porous materials and semi porous materials that are visibly mould should be able to be cleaned and reused.

#### **6.4.2 Porous Materials**

Porous materials with mould damage to more than a small area ( $>1 \text{ m}^2$ ) should be removed and discarded. Materials that can be cleaned can be remediate if necessary, but should be discarded if possible. Porous materials with mould growth to more than a small area should only be remediate by a professional restoration consultant. All porous materials that are remediate and returned to site should be dry and free of visible contamination and odours and should be periodically inspected to ensure the restoration was successful.

#### **6.4.3 Odour Control**

If ozone treatment is to be used for odour control, then the item must first undergo

restoration by drying and removing the mould growth with the recommended cleaning methods. The use of gaseous, vapour phase or aerosolised deodorants is not recommended. Using chemicals in this manner can cause adverse health effects in individuals returning to a site and occupants in adjacent areas.

### **6.5 Verification of Remediation Effectiveness**

The effectiveness of restoration to contents and remediation works to any larger sized job (Building Grade 3 or 4) should be verified by independent mould testing and analysis. In particular, large jobs that require high levels of containment and PPE should not be re-occupied until mycological testing has verified that the area is fit for re-habitation.

## **7 MOULD DAMAGE CLASSIFICATION SYSTEM**

The following classification system is to be used as a guide for mould remediators to help judge whether or not they are competent in managing the full extent of a remediation job. The building classification system includes the following types of mould damage:

1. BUILDING CLASS 1 - Normal
2. BUILDING CLASS 2 - Local Area Less Than  $1 \text{ m}^2$  (Cleaning to Remove Mould)
3. BUILDING CLASS 3 - Limited Visible Mould Growth to Less Than  $10 \text{ m}^2$  (Small Jobs)
4. BUILDING CLASS 4 - Extensive Visible Growth Greater Than  $10 \text{ m}^2$  (Large Jobs)
5. BUILDING CLASS 5 - Strong Indication of Mould Contamination but no Visible Evidence
6. BUILDING CLASS 6 - Cross Contamination
7. BUILDING CLASS 7 - Clean Room

### **7.1 BUILDING CLASS 1 - Normal**

Normal situation in most houses and buildings without mould damage. All fungi detected indoors would originally be from the outdoors as no indoor sources of mould should be present. Building Grade 1 situations can be entered using Level 1 PPE.

## **7.2 BUILDING CLASS 2 - Local Area Less Than 1 m<sup>2</sup> (Cleaning to Remove Mould)**

This level of building class refers to the initial inspection and sample taking process and to very small areas of visible mould growth that can be effectively cleaned using relatively simple methods. In particular this refers to either a small area of visible growth less than 1m<sup>2</sup> in area, or the conditions normally experienced during an initial site assessment on small jobs when taking samples or drilling inspection holes for borescope etc.

Building Grade 2 situations should only be entered using Level 2 PPE. Containment of the entire work area should not be necessary. The work area should not be occupied during inspections, cleaning or removal of contents or materials. It should not be necessary to evacuate people in adjacent areas except those with prescribed illness listed on page 6. Local areas for cleaning or removal can be sealed in plastic where required.

Remediation can be performed by normal building maintenance personnel that have been trained in Mould Hazard Awareness, PPE, and effective methods for cleaning mould. The entrance and exit locations used by the remediation / cleaning personnel should be cleaned with a HEPA vacuum cleaner and damp wiped with a cloth and vinegar solution. All areas should be left dry and free from visible mould contamination and debris. No final mould clearance testing would normally be necessary.

## **7.3 BUILDING CLASS 3 - Limited Visible Mould Growth to Less Than 10 m<sup>2</sup> (Small Jobs)**

This classification concerns an indoor environment that has sustained serious mould damage over a period of time. The visible mould growth would be clearly visible on less than 25% of all surfaces or not greater than 10 m<sup>2</sup>.

Building Grade 3 situations should only be entered using Level 3 PPE. The work area should not be occupied during cleaning or the removal of contents or materials or during inspections. It should not be necessary to evacuate people in adjacent areas except those with prescribed illness listed on page 6.

Containment of the entire work area should be performed before remediation commences. This will include covering the work area with plastic sheeting and sealing the edges with

tape to contain dust and remediation debris. Dust suppression methods should be applied to any material before it is disturbed. The waste should be carefully collected and wrapped in plastic and disposed of off-site.

Remediation can be performed by building maintenance personnel that have been trained in Mould Hazard Awareness, PPE, and effective methods for cleaning mould and remediating building materials. The entrance and exit locations used by the remediation / cleaning personnel should be cleaned with a HEPA vacuum cleaner and damp wiped with a cloth and vinegar solution. All areas should be left dry and free from visible mould contamination and debris. Final mould clearance sampling is highly recommended and should include several air and surface sample. Occupants should be cautioned not to return to the remediate area until after mycological analysis has determined that target species have been controlled or eliminated.

## **7.4 BUILDING CLASS 4 - Extensive Visible Growth Greater Than 10m<sup>2</sup> (Large Jobs)**

This classification concerns an indoor environment that has sustained severe mould damage that has affected the structural integrity of building materials such as wall and ceiling linings. Visible mould growth occurs on greater than 25% or more than 10 m<sup>2</sup> on interior surfaces. Structural materials most likely have high moisture contents and will require specific drying.

Building Grade 4 situations should only be performed using Level 4 PPE. The work area should be clearly marked with a sign stating "Biohazard Do Not Enter" during the entire remediation period. A list of remediation works and a completion schedule should be posted near the Biohazard sign. Hazard communication measures listed in page 6 should be made available to all people in adjacent areas.

Containment of the entire work area should be performed before remediation commences. This will include covering the work area and immediate adjacent areas with plastic sheeting and sealing the edges with tape to contain dust and remediation debris. HVAC, ventilation and exhaust ducts should be sealed with plastic and the edges taped to prevent remediation dust from further contaminating them.

The area should be placed under negative pressure by using an exhaust fan with a HEPA filter. Air scrubbers can be used as an area dust and spore suppression method. The entrance to the work area should be controlled through an air lock and decontamination room. These can be constructed from plastic sheeting over a demountable frame. All edges should be sealed with tape.

The work area should not be occupied during cleaning, removal of contents or materials or during inspections. It may be necessary to evacuate people in adjacent areas especially those with prescribed illness listed on page 6.

Any materials or contents that cannot be cleaned should be removed by wrapping in plastic bags. The outside of the plastic bags should be HEPA vacuum cleaned in the decontamination chamber before transporting through uncontaminated areas for disposing off-site in normal rubbish disposal. Dust suppression methods should be applied to any material before it is disturbed.

Remediation should be performed by personnel that have been trained in handling hazardous materials. The remediation area and the air lock and decontamination chamber and their immediate surrounds should be left dry and free from visible mould contamination and debris.

Extensive air and surface monitoring should be conducted in the remediate area. Occupants should only be allowed to return to the remediate area until after mycological analysis has determined that the area is fit to re-occupy.

### **7.5 BUILDING CLASS 5 - Strong Indication of Mould but no Visible Evidence**

Remediation should not commence until the building has been properly assessed. This class of mould damage might be characterised by any of the following situations:

1. Complaints of health symptoms with no visible growth,
2. Complaints of obnoxious mouldy odours with no visible growth,
3. Signs of structural weakness such as visible destruction to timber or dry rot,
4. Evidence of previous moisture damage that was dried but there are complaints of odours or symptoms but no visible growth
5. Other consultants have measured high concentrations of parameters such as

MVOCs or VOCs without any obvious source.

The source for symptoms in this situation needs to be thoroughly investigated.

The level of PPE required to enter a Building Grade 5 for investigation will vary according to the situation at hand.

- Level 2 PPE should be used where there is little evidence of widespread damage and no health complaints,
- Level 3 PPE should be used where there have been some health symptoms reported by individuals or mouldy odours etc.
- Level 4 PPE should be used if there have been serious symptoms or strong odours reported or where the investigator is to remain in the building for more than 30 minutes.

The work area should not be occupied during inspections. It may be necessary to warn people in adjacent areas of the potential hazards especially those with prescribed illness listed on page 6.

No remediation should proceed until the building has been thoroughly assessed by a qualified Mould Inspector or IAQ Assessor.

### **7.6 BUILDING CLASS 6 - CROSS CONTAMINATION**

This classification concerns an indoor environment that was Building Grade 1, but has been contaminated by spores and dust that originated from a Building Grade 2, 3 or 4. This can occur where remediation has been performed to adjacent areas and the containment procedures have not been followed, or where containment barriers have failed.

This may include small areas of visible growth (colonies less than 1mm diameter) that have occurred from the recent settling of spores, which have encountered sufficient moisture to begin growth.

This situation can only be returned to Building Grade 1 if the cross contamination is dealt with in a timely manner. If this situation is left for a period greater than 48 hours, or when widespread visible mould growth occurs, then the remediation works will need to be conducted as either Building Grade 2, 3 or 4 depending on the extent of the damage.

Building Grade 6 situations should only be remediate according to the level of contamination:

- Level 2 PPE should be used where there is minor evidence such as low concentrations of target species detected on surface or airborne samples.
- Level 3 PPE should be used if there is moderate or high evidence such as high levels of target species from the adjacent remediation area in surface and/or airborne samples.

The work area should not be occupied during remediation. In cases of high evidence of cross contamination, it may be necessary to warn or evacuate people in adjacent areas due to potential hazards especially those with prescribed illness listed on page 6.

Large areas with high concentrations of target species should be sealed with plastic and taped at the edges to prevent further cross contamination during cleaning. All cleaning should be thorough or meticulous with a high efficiency vacuum cleaner with a HEPA filter and a damp cloth and vinegar solution.

Remediation should be a thorough or meticulous cleaning with a high efficiency vacuum cleaner with a HEPA filter and a damp cloth and vinegar solution on all surfaces to removed settled spores and dust.

The entrance and exit locations used by the remediation / cleaning personnel should be thoroughly or meticulously cleaned with a high efficiency vacuum cleaner with a HEPA filter and a damp cloth and vinegar solution.

## **7.7 BUILDING CLASS 7**

### **HVAC Systems**

This section is in review and will be available soon. In principle the remediation should be performed according to the amount of fungal contamination as described in Building Grades 1 through 6. Extra PPE requirements may be required if workers are to be working in confined spaces.

## **7.8 BUILDING CLASS 7 - CLEAN ROOM**

This classification is for absolute sterilised clean room environments such as those used in pharmaceuticals and computer component manufacture. Only highly qualified and experienced Engineers and IAQ experts should only be consulted in these situations.

Protocols for handling Building Grade 4 Remediation work should be followed.

## **8 PPE CLASSIFICATION SYSTEM**

This classification system details the personal protection equipment (PPE) required to minimise exposure to fungal spores and/or fungal gaseous by-products during inspections and remediation works.

The person performing an inspection or in charge of remediation works should use their judgment and increase their level of PPE to suit the conditions at hand.

### **8.1 PPE LEVEL 1**

This level of PPE is intended for initial inspections or sampling regimes in Grade 1 buildings where there is no visible mould growth; health complaints; mould odours; cross contamination; or any known or obvious moisture damage. A breathing mask should not be required. No protective clothing should be required.

### **8.2 PPE LEVEL 2**

This level of PPE is intended for initial inspections or sampling regimes where mould growth is suspected due to known water damage or limited visible growth. There should be no serious health complaints related to mould or time spent in the building. A minimum of a half face respirator mask with disposable HEPA filters is recommended for extended periods. Where there are strong or obnoxious odours, then an activated carbon or organic vapour filter should be used in addition to the HEPA filter. No protective clothing such as overalls should be required. Breathing mask and gloves should be taken off outdoors.

### **8.3 PPE LEVEL 3**

This level of PPE is for small fungal contamination that relates to Building Grade 3 mould damage. The objective of this level of PPE is to limit exposure to fungal spores and gaseous by-products. A half face respirator mask with HEPA filters and splash goggles should be worn at all times. Where there are strong or obnoxious odours, then a full face mask should be used with an activated carbon or organic vapour filter in addition to the HEPA

filter. PPE should include disposable overalls and gloves.

#### **8.4 PPE LEVEL 4**

This level of PPE is for a maximum of 2 hour exposure to large area of fungal contamination that relates to Building Grade 4 mould damage. This level of PPE should eliminate exposure to fungal spores and gaseous by-products. PPE should include disposable overalls, gloves and shoe protectors. All joins at ankles and wrists where gloves and shoe protectors meet the disposable overalls should be sealed with tape. Full face respirator mask with HEPA filtration with an activated carbon or organic vapour filter should be used at all times.

## 9 GLOSSARY

|                          |                                                                                                                                                            |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>µg</b>                | micrograms                                                                                                                                                 |
| <b>µm</b>                | micrometers or microns                                                                                                                                     |
| <b>µg/m<sup>3</sup></b>  | micrograms per cubic metre                                                                                                                                 |
| <b>AC</b>                | air conditioner                                                                                                                                            |
| <b>agar</b>              | an extract of the cell walls of certain red algae that produces a jelly when dissolved in hot water                                                        |
| <b>AIHA</b>              | American Industrial Hygiene Association                                                                                                                    |
| <b>ASHRAE</b>            | American Society Of Heating Refrigerating And Air-conditioning Engineers                                                                                   |
| <b>a<sub>w</sub></b>     | water activity                                                                                                                                             |
| <b>Bulk Sample</b>       | taking a material samples from a surface either by scraping a hard surface or by vacuuming carpets or textiles                                             |
| <b>CBS</b>               | Centraalbureau voor Schimmelcultures                                                                                                                       |
| <b>CFU</b>               | colony forming unit                                                                                                                                        |
| <b>CFU/m<sup>2</sup></b> | colony forming units per square metre                                                                                                                      |
| <b>CFU/m<sup>3</sup></b> | colony forming units per cubic metre                                                                                                                       |
| <b>chlamydospore</b>     | resting spores that are formed from parts of vegetative hyphae                                                                                             |
| <b>CIH</b>               | Certified Industrial Hygienist                                                                                                                             |
| <b>cm</b>                | centimetre                                                                                                                                                 |
| <b>CO<sup>2</sup></b>    | carbon dioxide                                                                                                                                             |
| <b>colony</b>            | a consistent mycelium (mould) or a mass of cells (yeasts) that are of one origin                                                                           |
| <b>conidia</b>           | An exclusive form of reproduction only found in fungi that is not produced by cytoplasmic cleavage or free cell formation, commonly referred to as spores. |
| <b>contamination</b>     | fungal growth that is considered detrimental to materials or human health                                                                                  |
| <b>CzD</b>               | Czapek-Dox agar                                                                                                                                            |
| <b>DG 18</b>             | dichloran-18% glycerol agar, often misquoted as a xerophilic agar                                                                                          |
| <b>DNA</b>               | deoxyribonucleic acid                                                                                                                                      |
| <b>DRBC</b>              | dichloran rose Bengal chloramphenicol agar                                                                                                                 |

|                        |                                                                                                                                                                                                                                                                                      |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Fungi</b>           | any microorganisms belonging to the Kingdom Fungi including mould and yeast, commonly referred to as mould, though mould only refers to mycelial growing fungi                                                                                                                       |
| <b>g</b>               | grams                                                                                                                                                                                                                                                                                |
| <b>Genera</b>          | part of the taxonomic description of a group of fungi                                                                                                                                                                                                                                |
| <b>HEPA</b>            | High Efficiency Particulate Filtration: 99% efficiency of particles larger than 0.3 microns                                                                                                                                                                                          |
| <b>HEPA vacuum</b>     | A high efficiency vacuum cleaner with a HEPA filter, check that the HEPA filter holder is well designed sealed and does not allow bypass.                                                                                                                                            |
| <b>Hg</b>              | mercury                                                                                                                                                                                                                                                                              |
| <b>HVAC</b>            | heating ventilation and air conditioning system                                                                                                                                                                                                                                      |
| <b>hyphae</b>          | a part of filamentous growing fungi that is able to elongate                                                                                                                                                                                                                         |
| <b>IA</b>              | indoor air                                                                                                                                                                                                                                                                           |
| <b>IAP</b>             | Indoor air pollution                                                                                                                                                                                                                                                                 |
| <b>IAQ</b>             | indoor air quality                                                                                                                                                                                                                                                                   |
| <b>IAQ Assessor</b>    | An air quality or indoor environmental professional with training and extensive experience with indoor air quality (IAQ), sick building syndrome (SBS) and building related illness (BRI), may include and IAQ consultant, Industrial Hygienist, Occupational hygienist, or similar. |
| <b>IEA</b>             | indoor environmental assessment                                                                                                                                                                                                                                                      |
| <b>IEQ</b>             | indoor environment Quality                                                                                                                                                                                                                                                           |
| <b>IICRC</b>           | Institute Of Inspection Cleaning And Remediation Certification                                                                                                                                                                                                                       |
| <b>MEA</b>             | malt extract agar                                                                                                                                                                                                                                                                    |
| <b>MEA+40</b>          | malt extract agar + 40% Sucrose, a true xerophilic agar                                                                                                                                                                                                                              |
| <b>mg</b>              | milligram                                                                                                                                                                                                                                                                            |
| <b>MLA</b>             | Mycologia Australia Pty Ltd                                                                                                                                                                                                                                                          |
| <b>mm</b>              | millimetre                                                                                                                                                                                                                                                                           |
| <b>Mould</b>           | Common description of visible fungal colonies with mycelial growth form                                                                                                                                                                                                              |
| <b>Mould Inspector</b> | A qualified Mycologist with special training or experience in diagnosing building related mould problems.                                                                                                                                                                            |
| <b>MSDS</b>            | manufacturer safety data sheet                                                                                                                                                                                                                                                       |

|                        |                                                                                                                                                                               |                         |                                                                                                                                                          |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>MVOC</b>            | microbial volatile organic compound                                                                                                                                           | <b>substrate</b>        | the space in which a fungus grows and the material filling this space that provides nutrients for the fungus                                             |
| <b>mycelia</b>         | a single fungal hyphae                                                                                                                                                        |                         |                                                                                                                                                          |
| <b>mycelium</b>        | a mat of many individual hyphae woven together, often visible                                                                                                                 | <b>Surface Swab</b>     | Usually a sterile cotton tip swab dipped in sterile water and rubbed on a surface to pick up fungal spores and then transferred them to a nutrient agar. |
| <b>Mycologist</b>      | A person who works with fungi, similar to a microbiologist (who work mainly with bacteria)                                                                                    |                         |                                                                                                                                                          |
| <b>Mycology</b>        | The study of fungi                                                                                                                                                            | <b>Taxa</b>             | A term used in the systematic categorisation of fungal genera and species.                                                                               |
| <b>mycotoxin</b>       | A secondary metabolite produced by fungi as a normal part of respiration.                                                                                                     | <b>TSP</b>              | total suspended particulates                                                                                                                             |
| <b>n</b>               | sample number                                                                                                                                                                 | <b>UV</b>               | ultra violet                                                                                                                                             |
| <b>NIOSH</b>           | National Institute Of Occupation Safety And Health                                                                                                                            | <b>VC</b>               | vacuum cleaner                                                                                                                                           |
| <b>nutrient media</b>  | an agar with nutrients added to promote fungal growth and sporulation                                                                                                         | <b>vegetative state</b> | mycelium that have no reproductive structures                                                                                                            |
| <b>NYC DOHMH</b>       | New York City Department of Health and Mental Hygiene                                                                                                                         | <b>VOC</b>              | volatile organic compound                                                                                                                                |
| <b>OA</b>              | outdoor air                                                                                                                                                                   | <b>WME</b>              | Wood Moisture Equivalent                                                                                                                                 |
| <b>°C</b>              | degrees Celsius                                                                                                                                                               | <b>Yeast</b>            | Fungi that produce distinct cells and that reproduce by budding or dividing cells                                                                        |
| <b>PCR</b>             | polymerase chain reaction                                                                                                                                                     |                         |                                                                                                                                                          |
| <b>PM<sub>10</sub></b> | particulate matter with an effective aerodynamic diameter of 10 microns or smaller                                                                                            | <b>μ</b>                | micro                                                                                                                                                    |
| <b>PPE</b>             | personal protective equipment                                                                                                                                                 | <b>μm</b>               | micrometre                                                                                                                                               |
| <b>ppm</b>             | parts per million                                                                                                                                                             |                         |                                                                                                                                                          |
| <b>RH</b>              | relative humidity                                                                                                                                                             |                         |                                                                                                                                                          |
| <b>RODAC</b>           | A type of surface sampling where a modified agar plate is overfilled with nutrient agar so that the agar is sits proud and can be contacted with a surface and fungal spores. |                         |                                                                                                                                                          |
| <b>RSP</b>             | respirable particulate matter                                                                                                                                                 |                         |                                                                                                                                                          |
| <b>SBS</b>             | sick building syndrome                                                                                                                                                        |                         |                                                                                                                                                          |
| <b>SNA</b>             | synthetic low-nutrient agar                                                                                                                                                   |                         |                                                                                                                                                          |
| <b>sp.</b>             | Several species belonging to that genus.                                                                                                                                      |                         |                                                                                                                                                          |
| <b>spec.</b>           | A single fungal species was differentiated but not identified.                                                                                                                |                         |                                                                                                                                                          |
| <b>Species</b>         | the specific taxonomic description of a fungus                                                                                                                                |                         |                                                                                                                                                          |
| <b>Spore</b>           | A general term referring to all fungal reproductive structures including the spores from sexual reproduction and conidia from asexual reproduction and resting sclerota.      |                         |                                                                                                                                                          |
| <b>sporulation</b>     | the process where a fungus produces spores or conidia                                                                                                                         |                         |                                                                                                                                                          |
| <b>sterile mycelia</b> | A fungal colony containing fungi growing in a vegetative state.                                                                                                               |                         |                                                                                                                                                          |

## 10 BIBLIOGRAPHY AND REFERENCE DOCUMENTS

- ACGIH (1999) Bioaerosols: Assessment and Control. American college of Governmental Industrial Hygienists.
- ACGIH, (1989) *Guidelines for the Assessment of Bioaerosols in the Indoor Environment*. American Conference of Governmental Industrial Hygienists, Cincinnati, Ohio.
- AS 1668.2 (1991). Australian Standard 1668.2. *The use of mechanical ventilation and air-conditioning in buildings - Mechanical ventilation for acceptable indoor-air quality*. Standards Association of Australia, North Sydney, N.S.W., Australia.
- ASHRAE, standard 62 (1989) *Ventilation for Acceptable Indoor Air Quality*. American Society of Heating, Refrigerating, and Air-Conditioning Engineers, Atlanta, GA.
- Burge, H.A. (1995) Bioaerosol Investigations. In: *Indoor air research series: Bioaerosols*. Harriet A. Burge, Editor. CRC Press Inc., Boca Raton, Florida. pp. 1-24.
- Burge, H.A., Pierson, D.L., Groves, T.O., Strawn, K.E. and Mishra, S.K. (2000). Dynamics of airborne fungal populations in a large office building. *Curr. Microbiol.*, 40 (1): 10-16.
- C. Cheong, H.G. Neumeister-Kemp, P. Dingle, and G. E. St J. Hardy. (2004) Intervention study of airborne fungal spora in homes with portable HEPA filtration units. *J. Environ. Monit.*, 6: 866 - 873
- California Department of Health Services (2001) Indoor Air Quality Info Sheet
- CEC, (Commission of the European Communities) Working group No. 5, (1991) Wanner, H.-U. Chairman. *Indoor air quality and its impact on man - Report No. 12, Biological particles in indoor environments*. Brussels: ECSC-EEC-EAEC.
- de Hoog, G. S. (1972) The Genera *Beauveria*, *Isaria*, *Trithirachium* and *Acrodontium*. *Studies in Mycology*, No. 1, Centraalbureau voor Schimmelcultures, Baarn.
- de Hoog, G. S., Smith, M.Th., Guacho, E. (1986) *A Revision Of the Genus Geotrichum and its teleomorph*, Centraalbureau voor Schimmelcultures, Baarn.
- de Hoog, G.S., Guarro, J., Gené, J. and Figueras, M.J. (2000) *Atlas of Clinical Fungi* (2<sup>nd</sup> Edition), Centraalbureau voor Schimmelcultures, Baarn and Delft, Netherlands.
- Flannigan, B. (1994a) Biological Particles in the Air of Indoor Environments. In: Johanning, E. and Yang, S. (Eds.) *Fungi and Bacteria in Indoor Air Environments*. In: *Proceedings of the International Conference*. Saratoga Springs, Eastern New York Occupational Health Program, Latham, New York, USA., pp. 21-30.
- Flannigan, B. (1994b) Guidelines for Evaluation of Airborne Microbial Contamination. In: Eds.: Johanning, E. and Yang, S. *Fungi and Bacteria in Indoor Air Environments*. In: *Proceedings of the International Conference*. Saratoga Springs, Eastern New York Occupational Health Program, Latham, New York, USA., pp. 123-130.
- Flannigan, B. and Miller, J.D. (1994) *Health Implications of Fungi in Indoor Environments - an overview*. In: *Health Implications of Fungi in Indoor Environments*. (Eds.) R.A. Samson, B. Flannigan, M.E. Flannigan, A.P. Verhoeff, O.C.G. Adan, E.S. Hoekstra. Elsevier Science B.V. Amsterdam, The Netherlands. pp. 3-28.
- Garrett, M., Abramson, M.H.J., Hooper, B.M., Rayment, P.R., Strasser, R.P., and Hooper, M.A., (1998b) Indoor Environmental Risk Factors for Respiratory Health in Children.
- Garrett, M.H., Rayment, P.R., Hooper, M.A., Abramson, M.J., Hooper B.M. (1998a) Indoor airborne fungal spores, house dampness and associations with environmental factors and respiratory health in children. *Clin. Exp. Allergy*, 28(4), pp. 459-67.
- Godish, D., Godish, T., Hooper, B.M., Hooper, M.A., and Cole, M. (1996a) Airborne Mould Levels and Related Environmental Factors in Australian Houses, *Indoor and Built Environment*, 5, 148-54.
- Godish, T. (1995) *Sick buildings; definition diagnosis and mitigation*. Lewis Publishers, CRC Press, Boca Raton, Florida. pp. 171-194, 288-301.
- Gravesen, S., Frisvad, J.C., and Samson, R.A. (1994) *Microfungi*. Munksgaard, Copenhagen. pp. 9-26, 43-64.
- Hake, W. (1998) *Abscheidung von Mikroorganismen durch Filter in raumluftechnischen Anlagen; Qualitative und halb-qualitative Bestimmung der Mikroorganismen hinsichtlich ihrer Lungengängigkeit*. Doktor Arbeit Thesis, Centrale

- Bibliothek, Freie Universität Berlin, Berlin, Germany.
- Hake, W., Neumeister-Kemp, H.G., Kemp, P.C. and Martiny, H. (1999) Reduction of micro-organisms by HVAC System Filters and Analysis of the micro-organisms passing
- Health Canada, Environmental Health Directorate (1995) Fungal contamination in Buildings: A guide to recognition and management
- Hunter, C.A. and Bravery, A.F. (1989) Requirements for growth and control of surface moulds in dwellings. In: *Airborne Deteriogens and Pathogens* (ed. Flannigan, B.) Biodeterioration Society, Kew, Surrey, pp. 174-182.
- Hunter, C.A., and Lea, R.G. (1994) The airborne fungal population of representative British homes. In: Samson, R. A., Flannigan B., Flannigan M. E., Verhoeff A. P., Adan O. C. and Hoekstra E. (1994) *Health Implications of Fungi in Indoor Environments*. Amsterdam: Elsevier, pp. 141-153.
- IICRC S500 (1999) Standard and Reference guide for Professional Water Damage Restoration
- IICRC S520 (2003) Standard and reference guide for professional mould remediation. Institute of inspection, cleaning and restoration certification (IICRC).
- Jennings, D.H. and Lysek, G. (2001) *Fungal Biology (2nd Edition)* BIOS Scientific Publishers Ltd. Oxford, UK. pp. 135-140.
- Jensen C., H. G. Neumeister and G. Lysek (1997). Nematophagus fungi - study by fluorescence microscopy and EDX-technique of the periodicity of trap formation in soil. *Biological Rhythm Research*, Vol. 28, Nr. 3, 255-264
- Jensen C., H. Neumeister-Kemp and G. Lysek (1998). Fluorescence Microscopy for the Observation of Nematophagus Fungi inside Soil: *Mycologist*, Vol. 12 Part 3, 107-111, BMS, England
- Jensen, C., Neumeister, H.G. and Lysek, G. (1997) Nematophagous fungi - study by fluorescence microscopy and EDX-technique of the periodicity of trap formation in soil. *Biological Rhythm Research*, Vol. 28, Nr.3, pp. 255-264 .
- Johanning, E. (1994) Fungi and Bacteria in Indoor Air Environments. In: *Proceedings of the International Conference*. Saratoga Springs, Eastern New York Occupational Health Program, Latham, New York, USA. pp. ix-xiii.
- Kemp P.C., Neumeister-Kemp H.G., Esposito B., Lysek G. and Murray F. (2003). Changes in Airborne Fungi from the Outdoors to the Indoor Air: Large Hvac Systems in Non-Problem Buildings in two Different Climates. *American Industrial Hygiene Association Journal*, Vol. 66: March/April.
- Kemp P.C., Neumeister-Kemp H.G., Koch K., Lysek G. and Murray F. (2002). Determining the Growth and Vitality of Micro-organisms in Carpets and Mattresses in Non-Problem Dwellings by Measuring CO<sub>2</sub> Released during Respiration. *Indoor and Built Environment*. Vol. 11, pp. 214-220
- Kemp P.C., Neumeister-Kemp H.G., Lysek G. And Murray F. (2001). Survival and Growth of Micro-Organisms on Air Filtration Media during Initial Loading. *Atmospheric Environment*, Vol. 35/28, pp 4739-4749
- Kemp P.C., Neumeister-Kemp H.G., Murray F. And Lysek G. (2002). Airborne Fungi in Non-Problem Buildings in a Southern Hemisphere Mediterranean Climate: Preliminary Study of Natural and Mechanical Ventilation. *Indoor and Built Environment*. Vol. 11, pp. 44-53
- Kemp, P.C., Dingle, P., and Neumeister, H.G. (1998) Particulate Matter Intervention Study: A Causal Factor of Building-Related Symptoms in an older Building. *Indoor Air*, Munksgaard Press, Denmark, Vol. 9, pp. 153-171.
- Kemp, P.C., Neumeister, H.G., Kircheis, U., Franklin, P., Rüdén, and Murray, F. (1997) Fungal genera in an office building with a central HVAC system in an Australian Mediterranean climate. In: *Proceedings of Healthy Buildings/IAQ '97 Global Issues and Regional Solutions*, ASHRAE Annual IAQ Conference and ISIAQ 5th International Conference on Healthy buildings. Washington DC, USA, Vol. 1, pp. 257-262.
- Kemp, Peter C. Peter Dingle and Heike G. Neumeister (1998). Particulate Matter Intervention Study: A Causal Factor of Building-Related Symptoms in an older Building: *Indoor Air*, Vol. 8, 153-171, Munksgaard Press, Denmark
- Kircheis, U. (1997a) *Ökotoxikologische Untersuchungen an Pilzen zur Artverschiebung auf Luftfiltern von Klimaanlage*. Diploma Thesis, Centrale Bibliothek of the Freie Universität von Berlin, Berlin, Germany.
- Koch C., Neumeister H. and Wilke B.M. (1996). Wirkung ausgewählter PAK und PCB auf Mikroorganismen in

- Rieselfeldböden. Schriftenreihe: Landschaftsentwicklung & Umweltforschung, Band 101, 195-200 Berlin, Germany
- Kukkonen, E., Skaret, E., Sundell, J., and Valbjorn, O. (1993) Indoor climate problems; investigation and remedial measures. *Nordest Ventilation Group*, Finland. NT TECHN Report 204. pp. 2-96.
- Levetin, E. (1995) Fungi. In: *Bioaerosols: Indoor air research series*, Harriet A. Burge, Editor. CRC Press, Inc. Boca Raton, Florida. pp. 87-120.
- Lysek, G. (1984). Physiology and ecology of rhythmic growth and sporulation in fungi. In: *The Ecology and Physiology of the Fungal Mycelium*. Cambridge University Press, London. pp. 323-432.
- Miller, J.D. (1992) Fungi as contaminants in indoor air. *Atmospheric Environment*, Vol. 26a, No. 12, pp. 2163-2172.
- Neumeister H.G., M. Hesse and S. Quader (1997). Die Wirkung von ausgewählten PAK und PCB auf Pilze. In Bauer (Hrsg.) „Bodenökologische Untersuchungen zur Wirkung und Verteilung von organischen Stoffgruppen (PAK, PCB) in ballungsrautypischen Ökosystemen“. Zeitschrift des GSF-Forschungszentrum für Umwelt- und Gesundheit (GmbH), Neuherberg. 100-102, Germany
- Neumeister, H. (1990) „Untersuchung zum Wachstum von *Aspergillus alliaceus* im Hubstrahl-Bioreaktor“. Diplomarbeit thesis Titel Im Institut für Chemieingenieurtechnik der Technischen Universität Berlin, Berlin Germany.
- Neumeister, H. (1994). Nematophage Pilze: Entwicklung einer Präparations-technik für die Energiedispersive Röntgen-Mikroanalyse am Beispiel *Arthrobotrys oligospora*. Berlin Freie Universität, Dissertation 1993. In: Berichte aus der Biologie, Shaker Verlag Aachen 1994
- Neumeister, H., C. Koch, M. Emmrich and H. Rüdén (1996). Wirkung ausgewählter PAK's and PCB's auf das Wachstum der Hyphen, die Biomasseproduktion und die Keimung nematophager Pilze in vitro. Schriftenreihe: Landschaftsentwicklung & Umweltforschung, Band 101, 189-194
- Neumeister, H.G., Kemp, P C., Kircheis, U., Schleibinger, A. and Rüdén, P. (1997) Fungal growth on air filtration media in heating ventilation and air conditioning systems. In: *Proceedings of Healthy Buildings/IAQ '97 Global Issues and Regional Solutions*, Neumeister-Kemp, H.G., C. Cheong, P. Dingle, and G. E. St J. Hardy. (2004) Airborne viable indoor fungal levels and species in Australian residential homes following a carpet and soft furnishings cleaning intervention. *Atmospheric Environment* (in Press).
- Neumeister-Kemp, H.G., C.D. Cheong, P. C. Kemp, P. Dingle and G.E.St.J. Hardy (2001) Alteration in indoor fungal levels via portable HEPA air filters in bedrooms of asthmatic children, *Mycoses*, Vol. 44 No. 6, 244, Berlin Germany
- Neumeister-Kemp, Heike G., Aaron Maxwell, Peter C. Kemp, Giles E.St.J Hardy and Bernie Dell (2004) An advanced slit-type-volumetric-spore trap for monitoring bioaerosols; new methods for identifying fungal spores. *Australasian Plant Pathology* 33: 393-400.
- Neumeister-Kemp, Heike G., Cedric Cheong, Peter Kemp, Giles Hardy and Peter Dingle (2000). Indoor air fungi investigation of carpeted houses treated with different cleaning methods. *Mycoses*, Vol. 43 No. 6, 247, Berlin Germany
- Nevalainen, A., Pastuszka, J., Liebhaber, F., and Willeke, K. (1992) Performance of Bioaerosol Samplers: Collection Characteristics and Sampler Design Considerations. *Atmospheric Environment*. 26(A), pp. 531-540.
- Nordbring-Hertz B., H. Neumeister, K. Sjöllema and M. Veenhuis (1995). A conidial trap-forming mutant of *Arthrobotrys oligospora*. *Mycological Research*, 99 (11). 1395-1398
- NYC DOH (2002) Mould in my Home: What do I do? New York City Department of Health
- NYC DOHMH (2005) New York City Department of Health and Mental Hygiene. Environmentla & Occupational Disease Epidemiology; guidelines on assessment and remediation of fungi in indoor environments. Online at: <http://www.nyc.gov/html/doh/html/epi/moldrpt1.html> (accessed on 25/1/05).
- Pasanen, A.-L. (1994) Recent studies on fungal growth on building materials. In: *Health Implications of Fungi in Indoor Environments* (Eds. R.A. Samson et al.), Elsevier, Amsterdam, pp. 458-493.
- Pasenen, A.-L. (2001). A review: fungal exposure assessment in indoor environments. *Indoor Air*, 11:87-98.

- Portnoy et al.. (2004) Sampling for indoor Fungi. *J. Allergy Clin. Immunol.* Vol. 113, No. 2. pp 189-198
- Samson et al. (2002) Introduction to Food and Airborne Fungi, 6th Ed. Centraalbureau voor Schimmelcultures, Utrecht, Netherlands.
- Samson, R. A., Flannigan B., Flannigan M. E., Verhoeff A. P., Adan O. C. and Hoekstra E. (1994) *Health Implications of Fungi in Indoor Environments*. Amsterdam: Elsevier, pp. 531-538.
- Samson, R.A. Hoekstra, E.S., Frisvad, J.C. and Filtenborg, O. (1995) *Introduction to food borne fungi (4th Edition)* Centraalbureau voor Schimmelcultures, Baarn.
- Stetzenbach, L.D. (1992) Airborne Microorganisms. In: Lederberg J. (Ed), *Encyclopaedia of Microbiology*. Academic Press, Hardcourt Brace Janovich Publishers, San Diego, California.
- Stetzenbach, L.D., Hern S.C., and Seidler R.J. (1991) Field sampling design and experimental methods for the detection of airborne microorganisms. In: Levin M.A., Seidler R.J. and Rogul M. (Eds) *Microbial Ecology: Principles, Methods and Applications*. McGraw-Hill, Inc., New York.
- US EPA (2001) Mould Remediation in Schools and Commercial Buildings. United State Environmental Protection Agency.
- USEPA (1995) *The Inside Storey*. United States Environmental Protection Agency and the United States Consumer Product Safety Commission Office of Radiation and Indoor Air (6604J) EPA Document # 402-K-93-007, USEPA Information Clearinghouse, Washington, DC.
- Wanner, H.U., Verhoeff, A.P., Colombi, A., Flannigan, B., Gravesen, S., Mouilleseux, A., Nevalainen, A., Papadakis, J. and Seidel, K. (Eds.) (1993) *Biological Particles in Indoor Environments*. Indoor air quality and its impact on man, Environmental quality and life, Report No. 12, Commission of the European Communities, Brussels, pp. 81.
- Wilke, P. C. Kemp and H. G. Neumeister-Kemp (1999). A relationship between airborne fungi and bacteria with suspended particulates, VOCs and odours before, on and after the air filters of a HVAC system in a non-complaint building. *Mycoses*, Vol. 42 No. 3, 220-221, Berlin Germany
- Yang, C.S. (1994) Understanding the biology of fungi found indoors. In: *Proceedings of the International Conference Fungi and Bacteria in indoor Environments; Health effects, detection and remediation*. Saratoga Springs, New York. p. 131.

# MICROBIAL ASSESSMENT

## HELENSBURGH COMMUNITY CENTRE

26 WALKER STREET  
HELENSBURGH NSW 2508

**Client:**  
Quadracon Building Pty Ltd  
PO Box 249  
Moss Vale NSW 2577

| Reference:     | Revision:  | Date of Report: | Prepared By: | Authorised By:    |
|----------------|------------|-----------------|--------------|-------------------|
| 20-12361-01-OH | Revision 0 | 8/12/2020       | Luke Parkins | Michael Fernandez |
|                |            |                 |              |                   |
|                |            |                 |              |                   |
|                |            |                 |              |                   |
|                |            |                 |              |                   |

---

## Executive Summary

Clearsafe Environmental Solutions Pty Ltd (Clearsafe) was requested by Quadracon Building to undertake a limited assessment with regard to microbial levels within the subfloor space beneath the basketball court at the Helensburgh Community Centre, 26 Walker Street, Helensburgh NSW 2508. The investigation was commissioned following the identification of visible mould and broken timber joists within the subfloor of the Community centre during renovation works. Concerns were subsequently raised about the structural integrity of the timber floorboards and joists and any possible risk that the microbial impacts may present to any of the occupants within the immediate area during renovation.

Moisture level results for all of the measured timber building materials were above 10%, at the time of inspection. Moisture levels for timber surfaces above 10% are considered a trigger level for treatment/further assessment. It is noted that at the time of the inspection, water was visibly observed dripping from the timber joists/bearers throughout several locations within the subfloor and also on inspected brick wall surfaces within the subfloor (northern and western). The need for remediation and/or further investigation is recommended.

Surface swab analysis results indicate that all sampled locations returned detectable microbial concentrations at levels that suggest significant viable mould and bacteria. Samples 5 and 6 were unable to give accurate detectable yeast concentrations due to overgrown mould. However, all sample locations exhibited concentrations above double that of the reference sample, suggesting the need for further testing and/or remedial works. The mould count reported to the field blank sample is likely due to cross contamination and does not invalidate the results.

In conclusion, moisture readings in conjunction with surface swab analysis suggests that there is an underlying moisture ingress/microbial growth issue which appears to be present within the entirety of the basketball court subfloor. A visual inspection of the subfloor identified several timber bearers and timber joists that were either partially broken or had completely detached from their former position due to rot. Water was visually observed dripping from several of the timber joists within the subfloor and was also observed on the northern and western brick walls of the subfloor, coupled with what appeared to be a white powdery substance, which the inspecting consultant is of the belief is most likely efflorescence. Ground surfaces of the subfloor displayed evidence of dampness and trenches which appeared to be pathways for water ingress. A musty/damp odour was also present within the subfloor at the time of the inspection. Clearsafe recommends appropriate remediation as part of renovation.

---

The following recommendations apply to the microbial remediation works:

- Remediation work should be carried out by professional contractors in accordance with relevant guidelines and in consideration of the following points.
- The work area should not be occupied during cleaning processes.
- Conduct a building inspection by a professional building inspector to investigate the source of the water ingress within the subfloor, particular attention should be paid to the northern and western sides of the basketball court where the drainage extends from the exterior through the brick wall into the subfloor. Given the compromised structural integrity of the timber bearers and joists within the subfloor, Clearsafe recommends that access within it is restricted/limited.
- Clearsafe recommends that access to the basketball court by external parties (outside of companies working on behalf of the current scope of works) is completely restricted due to safety concerns posed by the structural integrity of the basketball court.
- Clearsafe is of the understanding that as a part of the original remediation works, Quadracon was engaged to remove a nominated section of the timber hardwood floors within the basketball court. Clearsafe suggests that the original scope of works is reassessed and extended to include the entirety of the timber hardwood floors due to the uniform nature of damage observed throughout the subfloor during the inspection. It is also suggested that further consideration be undertaken in regards to the replacement of the timber bearers and joists within the subfloor.
- As per the Australian Mould Guidelines, mould damage is classified into a class system based on the extent and visible microbial impacts observed. As the mould damage was visible throughout the entirety of the subfloor beneath the basketball court and is compromising the structural integrity of the timber hardwood floor, the remedial works would be classified as a **Building Class 4 - Extensive Visible Growth Greater Than 10m<sup>2</sup> (Large Job)**. As per these guidelines the area should be restricted and clearly signposted, ground surfaces within the subfloor covered in plastic sheets and HVAC, ventilation and exhaust ducts adequately sealed. A decontamination unit installed at one of the entrances to the basketball court and all other access points adequately sealed and placed under negative air pressure by using an exhaust fan with a HEPA filter. All timber materials to be disposed of should be wrapped in plastic bags and the external of the bags HEPA vacuumed in the decontamination unit prior to removal from the enclosure. PPE should include disposable overalls, gloves, shoe protectors and a full face respirator mask with HEPA filtration with an activated carbon or organic vapour filter.
- Throughout the course of the inspection fibrous cement fragments suspected of containing asbestos were observed sporadically scattered throughout the subfloor ground surfaces. Clearsafe recommends an emu pick of the ground surfaces, with

---

consideration given to conducting a scrape of 50-100mm of soils within the subfloor due to the incredibly damp and most likely microbial impacted nature of the soils. If any material suspected of containing asbestos is identified in the future (outside of that already identified), stop work immediately, restrict access to the impacted area and contact Clearsafe for further advice.

- Clearsafe is of the understanding that the western wall of the basketball court is also being replaced and new ventilation is being installed, it is recommended that the northern wall of the basketball court is also removed and replaced and adequate ventilation installed to allow for air flow within the subfloor.
- Post mould remediation works reduce the humidity within the basketball court subfloor by natural or artificial means (desiccant, dehumidifiers, increasing air flow).
- Post mould remediation works, increase natural light levels and ventilation within the basketball court subfloor.
- An Occupational Hygiene consultant should be contacted to conduct a final inspection and clearance testing following remediation work.

---

## Table of Contents

|                                           |                             |
|-------------------------------------------|-----------------------------|
| <b>1 Introduction and Scope</b>           | <b>5</b>                    |
| <b>2 Limitations</b>                      | <b>6</b>                    |
| <b>3 Sampling Details</b>                 | <b>7</b>                    |
| <b>4 Adopted Standards</b>                | <b>8</b>                    |
| <b>5 Observations</b>                     | <b>9</b>                    |
| <b>6 Moisture Level Spot Checks</b>       | <b>11</b>                   |
| <b>7 Surficial Microbial Sampling</b>     | <b>12</b>                   |
| <b>8 Conclusion</b>                       | <b>14</b>                   |
| <b>9 Recommendations</b>                  | <b>16</b>                   |
| <b>10 Closure and Contact Information</b> | <b>18</b>                   |
| <br><b>APPENDIX A</b>                     | <br><b>SITE PHOTOGRAPHS</b> |
| <b>APPENDIX B</b>                         | <b>LABORATORY REPORTS</b>   |

# 1 Introduction and Scope

Clearsafe Environmental Solutions Pty Ltd (Clearsafe) was requested by Quadracon Building to undertake a limited assessment with regard to microbial levels within the subfloor space beneath the basketball court at the Helensburgh Community Centre, 26 Walker Street, Helensburgh NSW 2508. The investigation was commissioned following the identification of visible mould and broken timber joists within the subfloor of the Community centre during renovation works. Concerns were subsequently raised about the structural integrity of the timber floorboards and joists and any possible risk that the microbial impacts may present to any of the occupants within the immediate area during renovation.

The agreed Scope of Work is summarised below:

- Moisture level spot checks in several locations throughout the subfloor using a hand-held moisture meter.
- Surficial microbial sampling (yeast, mould and bacteria) in eight (8) locations using sterilised swabs (Including a blank and reference sample)
- Visual inspection of the Helensburgh Community centre basketball court subfloor for visible evidence of water ingress and mould growth.
- Recommendations on the treatment of the mould and the surfaces affected.
- Preparation of a professional report summarising the findings of the investigation.

## 2 Limitations

All work is conducted in a conscientious and professional manner, with due diligence and appropriate care. However due to the disproportionate cost of potential damages or liability relative to the cost of our services, Clearsafe cannot offer any guarantee that all hazards have been identified. Subsequently, Clearsafe's liability to the client or any other party resulting from the performance or non-performance of the service, whether under contract law, tort law or otherwise, is limited to a maximum of up to five (5) times the total fee excluding expenses.

Clearsafe reports are not to be reproduced or reviewed except in full. All reports are prepared for a particular client's objective, and therefore should not be used by any third party as a basis for future decision-making.

Clearsafe relies on the accuracy of information provided by the client.

Any Party that uses or relies on this document, in doing so acknowledges, on behalf of themselves and all other legal entities that they represent, the unequivocal approval, acceptance and endorsement of the limitations and exclusions stated within this document, else this document should not be used or relied upon for any purpose.

### 3 Sampling Details

A site inspection and sampling was undertaken on the 27th of November 2020.

A TechCheck Plus (SN 13960) hand held moisture meter was used to undertake spot checks and measure relative moisture levels within representative building materials such as walls/ceiling surfaces and timber within a limited number of representative areas within the building.

Microbial samples were collected onto sterile, sealed and pre-packaged transport swabs/growth media using standard Clearsafe sampling procedures. The samples were transported in an iced insulated box and arrived at the nominated testing laboratory within 24hrs subsequent to the sampling.

Samples were collected from locations which were considered to be representative of the general conditions at the time of sampling.

The microbial sampling program was limited to surficial viable microorganisms in selected locations and during a specific period in time. Viable microorganism concentrations are known to vary markedly with differing meteorological and seasonal conditions.

## 4 Adopted Standards

Viable micro-organisms are common on urban surfaces and within indoor air. Microbial levels are relevant to indoor air quality as they can cause allergies and infections and may also negatively impact on an area's aesthetics by affecting surface coatings and releasing odorous volatile organic compounds.

The human body is well adapted to cope with most micro-organisms that are regularly encountered. As such it has not been possible for the scientific community to reproducibly establish levels of micro-organisms (on surfaces or in air) that are considered to be 'safe' or 'unsafe'.

The established methodology for assessing microbial levels is to collect samples from both affected and non-affected locations and make comparisons. It is common for there to be large variations detected between locations and therefore Clearsafe, in line with the industry accepted standard, uses the following triggers to indicate a need for remediation or further investigation:

- Evident mould growth as observed by a trained and experienced consultant.
- Microbial sample results greater than double (x2) the reference sample.

## 5 Observations

The site consists of the Helensburgh Community Centre located at 26 Walker Street Helensburgh. The primary area of concern for this report is within the subfloor of the Helensburgh Community Centre basketball court.

Clearsafe was advised the following information from the client:

- The timber floorboards of the western section (approximately  $\frac{1}{3}$ ) of the basketball courts were scheduled to be removed and replaced. A small section of the timber floorboards were removed (approximately 1m x 1.5m) and the client noticed the deteriorated condition of the timber joists and what appeared to be visible mould growth
- New ventilation is to be installed along the western wall of the basketball court
- The basketball court is hired out to external parties for use
- Mouldy/musty olfactory sensations had been reported within the subfloor of the basketball court

The following observations were noted during the inspection:

- A mouldy/musty odour was present within the subfloor of the basketball court at the time of the inspection
- The western section of the basketball court had been fenced off to restrict access
- Visible microbial growth was observed on the underside of the floorboards and on structural timber joists within the subfloor (refer to photos in Appendix A)
- The ground surfaces and timber joists/bearers within the subfloor were visibly damp in multiple locations, the timber bearers/joists were dripping with water at the time of the inspection
- A white growth was observed on the western and northern brick walls of the subfloor, both of which were also considerably wet
- Several timber joists and timber bearers within the subfloor had completely broken off and/or were significantly damaged compromising the timber floors structural integrity
- Viewed from above, several spots on the basketball court were visibly uneven
- Several fibrous cement fragments (presumed to be asbestos-containing) were found within the subfloor at the time of the inspection

- Pipes were observed along the western brick wall of the subfloor that extend from the outside of the building to within the subfloor (believed to be the source of the water ingress)

## 6 Moisture Level Spot Checks

### Method:

A Tech Check Plus hand held moisture meter was used to measure moisture within timber surfaces in several locations.

### Results:

Table 1: Moisture level of timber surfaces

| Location                                                                                                | Timber Surfaces (%)                                                           |
|---------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------|
| Internal, basketball court (western section), subfloor timber bearer immediately adjacent exposed entry | <b>Above instrument threshold (Tech Check Plus reading displayed as HIGH)</b> |
| Internal, basketball court (western section), subfloor timber joist immediately adjacent exposed entry  | <b>Above instrument threshold (Tech Check Plus reading displayed as HIGH)</b> |
| Internal, basketball court (western section), timber hardwood floor immediately adjacent exposed entry  | <b>12.7%</b>                                                                  |
| Internal, basketball court (central section), underside of timber joist                                 | <b>17.1%</b>                                                                  |
| Internal, basketball court (eastern section), underside of timber bearer                                | <b>15.6%</b>                                                                  |

### Discussion:

Moisture level results for all of the measured timber building materials were above 10%, at the time of inspection. Moisture levels for timber surfaces above 10% are considered a trigger level for treatment/further assessment. It is noted that at the time of the inspection, water was visibly observed dripping from the timber joists/bearers throughout several locations within the subfloor and also on inspected brick wall surfaces within the subfloor (northern and western). The need for remediation and/or further investigation is recommended.

## 7 Surficial Microbial Sampling

### Method:

Surficial microbial sampling was undertaken in eight (8) locations using swabs (Including a blank and reference sample). The swabs are used to collect microbial spores from direct contact with surfaces and are then placed onto growth media and incubated in a controlled environment, before being analysed for viable colony forming units (CFU). The results are then compared with control samples collected from a similar non-affected location nearby.

### Results:

Table 2: Surficial Microbial Counts Using Swabs

| Sample No.         | Location                                                                                                 | Bacteria Count (CFU/plate) | Yeast Count (CFU/plate) | Mould Count (CFU/plate) |
|--------------------|----------------------------------------------------------------------------------------------------------|----------------------------|-------------------------|-------------------------|
| 20-12361/<br>Blank | Field Blank                                                                                              | 10 est.                    | <10                     | <b>1100</b>             |
| 20-12361/<br>Ref   | Internal, basketball court, on fire hose reel box immediately adjacent southern entry                    | <10                        | <10                     | 10 est.                 |
| 20-12361/<br>S1    | Subfloor (beneath basketball court), on broken timber joist directly below western subfloor access point | <b>5000</b>                | <10                     | <b>1900</b>             |
| 20-12361/<br>S2    | Subfloor (beneath basketball court), on western brick wall                                               | <b>56000 est.</b>          | <10                     | <b>400</b>              |
| 20-12361/<br>S3    | Subfloor (beneath basketball court), on broken timber bearer immediately adjacent subfloor access point  | <b>5500</b>                | <10                     | <b>2200</b>             |
| 20-12361/<br>S4    | Subfloor (beneath basketball court), on northern brick wall                                              | <b>350</b>                 | <10                     | <b>500</b>              |

|                 |                                                                                                             |              |                                                   |                      |
|-----------------|-------------------------------------------------------------------------------------------------------------|--------------|---------------------------------------------------|----------------------|
| 20-12361/<br>S5 | Subfloor (beneath basketball court), centrally located, on underside of timber floorboards                  | <b>11000</b> | Unable to determine Yeast count due to TNTC mould | <b>&gt;3000 est.</b> |
| 20-12361/<br>S6 | Subfloor (beneath basketball court), on top surface of PVC pipe immediately adjacent eastern subfloor entry | <b>7200</b>  | Unable to determine Yeast count due to TNTC mould | <b>&gt;3000 est.</b> |

Note: est. = Estimated

#### Discussion:

With reference to Table 2, above, results indicate that all sampled locations returned detectable microbial concentrations at levels that suggest significant viable mould and bacteria. Samples 5 and 6 were unable to give accurate detectable yeast concentrations due to overgrown mould. However, all sample locations exhibited concentrations above double that of the reference sample, suggesting the need for further testing and/or remedial works. The mould count reported to the field blank sample is likely due to cross contamination and does not invalidate the results.

## 8 Conclusion

Clearsafe Environmental Solutions Pty Ltd (Clearsafe) was requested by Quadracon Building to undertake a limited assessment with regard to microbial levels within the subfloor space beneath the basketball court at the Helensburgh Community Centre, 26 Walker Street, Helensburgh NSW 2508. The investigation was commissioned following the identification of visible mould and broken timber joists within the subfloor of the Community centre during renovation works. Concerns were subsequently raised about the structural integrity of the timber floorboards and joists and any possible risk that the microbial impacts may present to any of the occupants within the immediate area during renovation.

Moisture level results for all of the measured timber building materials were above 10%, at the time of inspection. Moisture levels for timber surfaces above 10% are considered a trigger level for treatment/further assessment. It is noted that at the time of the inspection, water was visibly observed dripping from the timber joists/bearers throughout several locations within the subfloor and also on inspected brick wall surfaces within the subfloor (northern and western). The need for remediation and/or further investigation is recommended.

Surface swab analysis results indicate that all sampled locations returned detectable microbial concentrations at levels that suggest significant viable mould and bacteria. Samples 5 and 6 were unable to give accurate detectable yeast concentrations due to overgrown mould. However, all sample locations exhibited concentrations above double that of the reference sample, suggesting the need for further testing and/or remedial works. The mould count reported to the field blank sample is likely due to cross contamination and does not invalidate the results.

In conclusion, moisture readings in conjunction with surface swab analysis suggests that there is an underlying moisture ingress/microbial growth issue which appears to be present within the entirety of the basketball court subfloor. A visual inspection of the subfloor identified several timber bearers and timber joists that were either partially broken or had completely detached from their former position due to rot. Water was visually observed dripping from several of the timber joists within the subfloor and was also observed on the northern and western brick walls of the subfloor, coupled with what appeared to be a white powdery substance, which the inspecting consultant is of the belief is most likely efflorescence. Ground surfaces of the subfloor displayed evidence of dampness and trenches which appeared to be pathways for water ingress. A musty/damp odour was also present within the subfloor at the time of the inspection. Clearsafe recommends appropriate remediation as part of renovation.

As per the Australian Mould Guidelines, mould damage is classified into a class system based on the extent and visible microbial impacts observed. As the mould damage was visible throughout the entirety of the subfloor beneath the basketball court and is compromising the structural integrity of the timber hardwood floor, the remedial works would

---

be classified as a ***Building Class 4 - Extensive Visible Growth Greater Than 10m2 (Large Job)***.

---

## 9 Recommendations

The following recommendations apply to the microbial remediation works:

- Remediation work should be carried out by professional contractors in accordance with relevant guidelines and in consideration of the following points.
- The work area should not be occupied during cleaning processes.
- Conduct a building inspection by a professional building inspector to investigate the source of the water ingress within the subfloor, particular attention should be paid to the northern and western sides of the basketball court where the drainage extends from the exterior through the brick wall into the subfloor. Given the compromised structural integrity of the timber bearers and joists within the subfloor, Clearsafe recommends that access within it is restricted/limited.
- Clearsafe recommends that access to the basketball court by external parties (outside of companies working on behalf of the current scope of works) is completely restricted due to safety concerns posed by the structural integrity of the basketball court.
- Clearsafe is of the understanding that as a part of the original remediation works, Quadracon was engaged to remove a nominated section of the timber hardwood floors within the basketball court. Clearsafe suggests that the original scope of works is reassessed and extended to include the entirety of the timber hardwood floors due to the uniform nature of damage observed throughout the subfloor during the inspection. It is also suggested that further consideration be undertaken in regards to the replacement of the timber bearers and joists within the subfloor.
- As per the Australian Mould Guidelines, mould damage is classified into a class system based on the extent and visible microbial impacts observed. As the mould damage was visible throughout the entirety of the subfloor beneath the basketball court and is compromising the structural integrity of the timber hardwood floor, the remedial works would be classified as a **Building Class 4 - Extensive Visible Growth Greater Than 10m<sup>2</sup> (Large Job)**. As per these guidelines the area should be restricted and clearly signposted, ground surfaces within the subfloor covered in plastic sheets and HVAC, ventilation and exhaust ducts adequately sealed. A decontamination unit installed at one of the entrances to the basketball court and all other access points adequately sealed and placed under negative air pressure by using an exhaust fan with a HEPA filter. All timber materials to be disposed of should be wrapped in plastic bags and the external of the bags HEPA vacuumed in the decontamination unit prior to removal from the enclosure. PPE should include disposable overalls, gloves, shoe protectors and a full face respirator mask with HEPA filtration with an activated carbon or organic vapour filter.

- 
- Throughout the course of the inspection fibrous cement fragments suspected of containing asbestos were observed sporadically scattered throughout the subfloor ground surfaces. Clearsafe recommends an emu pick of the ground surfaces, with consideration given to conducting a scrape of 50-100mm of soils within the subfloor due to the incredibly damp and most likely microbial impacted nature of the soils. If any material suspected of containing asbestos is identified in the future (outside of that already identified), stop work immediately, restrict access to the impacted area and contact Clearsafe for further advice.
  - Clearsafe is of the understanding that the western wall of the basketball court is also being replaced and new ventilation is being installed, it is recommended that the northern wall of the basketball court is also removed and replaced and adequate ventilation installed to allow for air flow within the subfloor.
  - Post mould remediation works reduce the humidity within the basketball court subfloor by natural or artificial means (desiccant, dehumidifiers, increasing air flow).
  - Post mould remediation works, increase natural light levels and ventilation within the basketball court subfloor.
  - An Occupational Hygiene consultant should be contacted to conduct a final inspection and clearance testing following remediation work.

## 10 Closure and Contact Information

For any queries relating to this report, please contact Clearsafe on 1300 042 962 or [info@clearsafe.com.au](mailto:info@clearsafe.com.au).

Clearsafe is pleased to provide our consulting services for this commission.

Kind Regards,



**Luke Parkins**  
Project Consultant



**Michael Fernandez**  
Regional Manager

# **APPENDIX A**

## **SITE PHOTOGRAPHS**

| Photo                                                                              | Location                                                                                       |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|
|   | Representative photograph of the basketball court (including the western 'restricted' section) |
|  | Representative photograph of the western access point into the subfloor                        |



Representative photograph of one of the pipes along the western wall of the subfloor



Representative photograph of several floor timber joists that have partially broken and are coated with moisture



Representative photograph of one (of many) of the floor timber joists



Representative photograph of a broken floor timber joist within the subfloor



Representative photograph of a fractured floor timber bearer



Representative photograph of remnant fibrous cement sheeting within the subfloor



Representative photograph of fibrous cement packers supporting the timber bearers



Representative photograph of the northern brick wall within the subfloor



Representative photograph of a floor timber bearer immediately adjacent the northern brick wall

# **APPENDIX B**

## **LABORATORY REPORTS**

|             |                |
|-------------|----------------|
| COA No:     | SYD-51514163-0 |
| Supersedes: | None           |
| COA Date:   | 07/12/2020     |
| Page 1 of 5 |                |

**TO:**

Clearsafe Environmental Solutions  
 Clearsafe Environmental Solutions  
 PO Box 337  
 UNANDERRA, NSW 2526

|                |                |
|----------------|----------------|
| Received From: | Unanderra, NSW |
| Received Date: | 27/11/2020     |

|                                        |                   |
|----------------------------------------|-------------------|
| Location of Test: (except where noted) | Regents Park, NSW |
|----------------------------------------|-------------------|

## Analytical Results

|                                              |               |                |                         |                          |             |
|----------------------------------------------|---------------|----------------|-------------------------|--------------------------|-------------|
| Desc. 1: ^                                   |               | 20-12361/Blank |                         | Sample Number: 456455852 |             |
|                                              |               |                |                         | Condition Rec'd: NORMAL  |             |
|                                              |               |                |                         | Temp Rec'd (°C): 18.0    |             |
|                                              |               |                |                         | Date Started: 27/11/2020 |             |
| Results apply only to the sample as received |               |                |                         |                          |             |
| <u>Analyte</u>                               | <u>Result</u> | <u>Units</u>   | <u>Method Reference</u> | <u>Result Date</u>       | <u>Loc.</u> |
| Total Bacterial Count                        | 10 est.       | CFU/swab       | M17.2                   | 30/11/2020               |             |
| Total Mould Count                            | 1100          | CFU/swab       | M17.2                   | 02/12/2020               |             |
| Total Yeast Count                            | <10           | CFU/swab       | M17.2                   | 02/12/2020               |             |

|                                              |               |              |                         |                          |             |
|----------------------------------------------|---------------|--------------|-------------------------|--------------------------|-------------|
| Desc. 1: ^                                   |               | 20-12361/Ref |                         | Sample Number: 456455854 |             |
|                                              |               |              |                         | Condition Rec'd: NORMAL  |             |
|                                              |               |              |                         | Temp Rec'd (°C): 18.0    |             |
|                                              |               |              |                         | Date Started: 27/11/2020 |             |
| Results apply only to the sample as received |               |              |                         |                          |             |
| <u>Analyte</u>                               | <u>Result</u> | <u>Units</u> | <u>Method Reference</u> | <u>Result Date</u>       | <u>Loc.</u> |
| Total Bacterial Count                        | <10           | CFU/swab     | M17.2                   | 30/11/2020               |             |
| Total Mould Count                            | 10 est.       | CFU/swab     | M17.2                   | 02/12/2020               |             |
| Total Yeast Count                            | <10           | CFU/swab     | M17.2                   | 02/12/2020               |             |



Accredited for compliance with ISO/IEC 17025 - Testing  
 NATA Corporate Accreditation Number: 2020  
 Melbourne Microbiology Site No: 2013  
 Sydney Microbiology Site No: 2759 Chemistry Site No: 2135  
 Perth Microbiology Site No: 10635  
 Brisbane Microbiology Site No: 15147  
 This document shall not be reproduced except in full.

**^ Customer supplied information**

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s). The data therefore may not be representative of the lot or batch or other samples.

This report shall not be reproduced except in full.  
 Measurement Uncertainty (MU) can be found by logging in to MyMXNS

TGA Licence No: MI-04072005-LI-000664-2

AU-COA-33 v8

|             |                |
|-------------|----------------|
| COA No:     | SYD-51514163-0 |
| Supersedes: | None           |
| COA Date:   | 07/12/2020     |
| Page 2 of 5 |                |

**TO:**

Clearsafe Environmental Solutions  
 Clearsafe Environmental Solutions  
 PO Box 337  
 UNANDERRA, NSW 2526

|                |                |
|----------------|----------------|
| Received From: | Unanderra, NSW |
| Received Date: | 27/11/2020     |

**Location of Test: (except where noted)**  
 Regents Park, NSW

## Analytical Results

|                                              |                      |                     |                                |                                 |                    |
|----------------------------------------------|----------------------|---------------------|--------------------------------|---------------------------------|--------------------|
| <b>Desc. 1: ^</b>                            |                      | 20-12361/S1         |                                | <b>Sample Number:</b> 456455855 |                    |
|                                              |                      |                     |                                | <b>Condition Rec'd:</b> NORMAL  |                    |
|                                              |                      |                     |                                | <b>Temp Rec'd (°C):</b> 18.0    |                    |
|                                              |                      |                     |                                | <b>Date Started:</b> 27/11/2020 |                    |
| Results apply only to the sample as received |                      |                     |                                |                                 |                    |
| <b><u>Analyte</u></b>                        | <b><u>Result</u></b> | <b><u>Units</u></b> | <b><u>Method Reference</u></b> | <b><u>Result Date</u></b>       | <b><u>Loc.</u></b> |
| Total Bacterial Count                        | 5000                 | CFU/swab            | M17.2                          | 30/11/2020                      |                    |
| Total Mould Count                            | 1900                 | CFU/swab            | M17.2                          | 02/12/2020                      |                    |
| Total Yeast Count                            | <10                  | CFU/swab            | M17.2                          | 02/12/2020                      |                    |

|                                              |               |              |                         |                          |             |
|----------------------------------------------|---------------|--------------|-------------------------|--------------------------|-------------|
| Desc. 1: ^                                   |               | 20-12361/S2  |                         | Sample Number: 456455856 |             |
|                                              |               |              |                         | Condition Rec'd: NORMAL  |             |
|                                              |               |              |                         | Temp Rec'd (°C): 18.0    |             |
|                                              |               |              |                         | Date Started: 27/11/2020 |             |
| Results apply only to the sample as received |               |              |                         |                          |             |
| <u>Analyte</u>                               | <u>Result</u> | <u>Units</u> | <u>Method Reference</u> | <u>Result Date</u>       | <u>Loc.</u> |
| Total Bacterial Count                        | 56000 est.    | CFU/swab     | M17.2                   | 30/11/2020               |             |
| Total Mould Count                            | 400           | CFU/swab     | M17.2                   | 02/12/2020               |             |
| Total Yeast Count                            | <10           | CFU/swab     | M17.2                   | 02/12/2020               |             |



Accredited for compliance with ISO/IEC 17025 - Testing  
 NATA Corporate Accreditation Number: 2020  
 Melbourne Microbiology Site No: 2013  
 Sydney Microbiology Site No: 2759 Chemistry Site No: 2135  
 Perth Microbiology Site No: 10635  
 Brisbane Microbiology Site No: 15147  
 This document shall not be reproduced except in full.

**^ Customer supplied information**

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s). The data therefore may not be representative of the lot or batch or other samples.

This report shall not be reproduced except in full.  
 Measurement Uncertainty (MU) can be found by logging in to MyMXNS

TGA Licence No: MI-04072005-LI-000664-2

AU-COA-33 v8

|             |                |
|-------------|----------------|
| COA No:     | SYD-51514163-0 |
| Supersedes: | None           |
| COA Date:   | 07/12/2020     |
| Page 3 of 5 |                |

**TO:**

Clearsafe Environmental Solutions  
 Clearsafe Environmental Solutions  
 PO Box 337  
 UNANDERRA, NSW 2526

|                |                |
|----------------|----------------|
| Received From: | Unanderra, NSW |
| Received Date: | 27/11/2020     |

**Location of Test: (except where noted)**  
 Regents Park, NSW

## Analytical Results

|                                              |               |              |                         |                          |             |
|----------------------------------------------|---------------|--------------|-------------------------|--------------------------|-------------|
| Desc. 1: ^                                   |               | 20-12361/S3  |                         | Sample Number: 456455857 |             |
|                                              |               |              |                         | Condition Rec'd: NORMAL  |             |
|                                              |               |              |                         | Temp Rec'd (°C): 18.0    |             |
|                                              |               |              |                         | Date Started: 27/11/2020 |             |
| Results apply only to the sample as received |               |              |                         |                          |             |
| <u>Analyte</u>                               | <u>Result</u> | <u>Units</u> | <u>Method Reference</u> | <u>Result Date</u>       | <u>Loc.</u> |
| Total Bacterial Count                        | 5500          | CFU/swab     | M17.2                   | 30/11/2020               |             |
| Total Mould Count                            | 2200          | CFU/swab     | M17.2                   | 02/12/2020               |             |
| Total Yeast Count                            | <10           | CFU/swab     | M17.2                   | 02/12/2020               |             |

|                       |               |                                              |                         |                    |             |
|-----------------------|---------------|----------------------------------------------|-------------------------|--------------------|-------------|
| Desc. 1: ^            | 20-12361/S4   | Sample Number: 456455858                     |                         |                    |             |
|                       |               | Condition Rec'd: NORMAL                      |                         |                    |             |
|                       |               | Temp Rec'd (°C): 18.0                        |                         |                    |             |
|                       |               | Date Started: 27/11/2020                     |                         |                    |             |
|                       |               | Results apply only to the sample as received |                         |                    |             |
| <u>Analyte</u>        | <u>Result</u> | <u>Units</u>                                 | <u>Method Reference</u> | <u>Result Date</u> | <u>Loc.</u> |
| Total Bacterial Count | 350           | CFU/swab                                     | M17.2                   | 30/11/2020         |             |
| Total Mould Count     | 500           | CFU/swab                                     | M17.2                   | 02/12/2020         |             |
| Total Yeast Count     | <10           | CFU/swab                                     | M17.2                   | 02/12/2020         |             |



Accredited for compliance with ISO/IEC 17025 - Testing  
 NATA Corporate Accreditation Number: 2020  
 Melbourne Microbiology Site No: 2013  
 Sydney Microbiology Site No: 2759 Chemistry Site No: 2135  
 Perth Microbiology Site No: 10635  
 Brisbane Microbiology Site No: 15147  
 This document shall not be reproduced except in full.

**^ Customer supplied information**

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s). The data therefore may not be representative of the lot or batch or other samples.

This report shall not be reproduced except in full.  
 Measurement Uncertainty (MU) can be found by logging in to MyMXNS

TGA Licence No: MI-04072005-LI-000664-2

AU-COA-33 v8

|             |                |
|-------------|----------------|
| COA No:     | SYD-51514163-0 |
| Supersedes: | None           |
| COA Date:   | 07/12/2020     |
| Page 4 of 5 |                |

**TO:**

Clearsafe Environmental Solutions  
 Clearsafe Environmental Solutions  
 PO Box 337  
 UNANDERRA, NSW 2526

|                |                |
|----------------|----------------|
| Received From: | Unanderra, NSW |
| Received Date: | 27/11/2020     |

**Location of Test: (except where noted)**  
 Regents Park, NSW

## Analytical Results

|                                              |  |                         |              |                          |                    |
|----------------------------------------------|--|-------------------------|--------------|--------------------------|--------------------|
| Desc. 1: ^                                   |  | 20-12361/S5             |              | Sample Number: 456455859 |                    |
|                                              |  |                         |              | Condition Rec'd: NORMAL  |                    |
|                                              |  |                         |              | Temp Rec'd (°C): 18.0    |                    |
|                                              |  |                         |              | Date Started: 27/11/2020 |                    |
| Results apply only to the sample as received |  |                         |              |                          |                    |
| <u>Analyte</u>                               |  | <u>Result</u>           | <u>Units</u> | <u>Method Reference</u>  | <u>Result Date</u> |
| Total Bacterial Count                        |  | 11000                   | CFU/swab     | M17.2                    | 30/11/2020         |
| Total Mould Count                            |  | >3000 est.              | CFU/swab     | M17.2                    | 07/12/2020         |
| Total Yeast Count                            |  | Unable to determine the | CFU/swab     | M17.2                    | 07/12/2020         |
|                                              |  | Yeast Count due to TNTC |              |                          |                    |
|                                              |  | mould.                  |              |                          |                    |

|                                              |  |                           |              |                          |                    |
|----------------------------------------------|--|---------------------------|--------------|--------------------------|--------------------|
| Desc. 1: ^                                   |  | 20-12361/S6               |              | Sample Number: 456455860 |                    |
|                                              |  |                           |              | Condition Rec'd: NORMAL  |                    |
|                                              |  |                           |              | Temp Rec'd (°C): 18.0    |                    |
|                                              |  |                           |              | Date Started: 27/11/2020 |                    |
| Results apply only to the sample as received |  |                           |              |                          |                    |
| <u>Analyte</u>                               |  | <u>Result</u>             | <u>Units</u> | <u>Method Reference</u>  | <u>Result Date</u> |
| Total Bacterial Count                        |  | 7200                      | CFU/swab     | M17.2                    | 30/11/2020         |
| Total Mould Count                            |  | >3000 est.                | CFU/swab     | M17.2                    | 07/12/2020         |
| Total Yeast Count                            |  | Unable to determine Yeast | CFU/swab     | M17.2                    | 07/12/2020         |
|                                              |  | Count due to TNTC mould.  |              |                          |                    |



Accredited for compliance with ISO/IEC 17025 - Testing  
 NATA Corporate Accreditation Number: 2020  
 Melbourne Microbiology Site No: 2013  
 Sydney Microbiology Site No: 2759 Chemistry Site No: 2135  
 Perth Microbiology Site No: 10635  
 Brisbane Microbiology Site No: 15147  
 This document shall not be reproduced except in full.

**^ Customer supplied information**

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s). The data therefore may not be representative of the lot or batch or other samples.

This report shall not be reproduced except in full.  
 Measurement Uncertainty (MU) can be found by logging in to MyMXNS

TGA Licence No: MI-04072005-LI-000664-2

AU-COA-33 v8

|             |                |
|-------------|----------------|
| COA No:     | SYD-51514163-0 |
| Supersedes: | None           |
| COA Date:   | 07/12/2020     |
| Page 5 of 5 |                |

**TO:**

Clearsafe Environmental Solutions  
Clearsafe Environmental Solutions  
PO Box 337  
UNANDERRA, NSW 2526

|                |                |
|----------------|----------------|
| Received From: | Unanderra, NSW |
| Received Date: | 27/11/2020     |

**Location of Test: (except where noted)**  
Regents Park, NSW

---

---

**Analytical Results**

---

---



**GEORGE GEORGAS**  
LABORATORY MANAGER

**MXNS Abbreviations/Definitions:**

| <: Less Than | >: Greater Than | CFU: Colony Forming Units | D: Detected | ND: Not Detected | MPN: Most Probable Number | LOR: Level of Reporting | LOD: Level of Detection |  
| LOQ: Limit of Quantification | est.: Estimate |



Accredited for compliance with ISO/IEC 17025 - Testing  
NATA Corporate Accreditation Number: 2020  
Melbourne Microbiology Site No: 2013  
Sydney Microbiology Site No: 2759 Chemistry Site No: 2135  
Perth Microbiology Site No: 10635  
Brisbane Microbiology Site No: 15147  
This document shall not be reproduced except in full.

**^ Customer supplied information**

The data pertains solely to the analytical and sampling procedure(s) used and the condition and homogeneity of the sample(s). The data therefore may not be representative of the lot or batch or other samples.

This report shall not be reproduced except in full.  
Measurement Uncertainty (MU) can be found by logging in to MyMXNS

TGA Licence No: MI-04072005-LI-000664-2

AU-COA-33 v8